

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9500Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

06 OCT 2020

PART

- 1 COVER, REAR BUMPER
1 REINFORCEMENT SUB-ASSY, REAR BUMPER
1 COVER, REAR BUMPER, LOWER
1 GUARD, REAR BUMPER, CENTER
1 RETAINER, REAR BUMPER SIDE, LH
1 PANEL SUB-ASSY, BACK DOOR
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1 WEATHERSTRIP, BACK DOOR
1 PANEL SUB-ASSY, BODY LOWER BACK
1 LENS AND BODY, REAR LAMP, LH
1 LENS & BODY, REAR COMBINATION LAMP, LH
1 FILLER, REAR BUMPER EXTENSION, LH
1 COVER, REAR FLOOR
1 COVER, FLOOR UNDER, NO.2
1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH

XSVC

SHD 9500Z

JTDKB3FU403080996

TOYOTA

PRIUS

5.10.2020

TOKIO MARINE

31/05/2019

LIST

\$	Bur	442.60	✓
\$	nut	332.70	✓
\$	sn	15.40	X
\$	nut	576.30	✓
\$	sn	116.50	
\$	n	1,147.80	
\$	sn	925.60	
\$	sn	372.30	
\$	n	650.30	
\$	sn	502.00	
\$	sn	443.30	
\$	sn	123.70	
\$	sn	229.90	
\$	sn	241.90	
\$	sn	56.50	

TOTAL \$ 6,176.80**25% \$ 1,544.20****\$ 4,632.60****Special Nett**

- 1SET PARKING AID
1SET REAR BUMPER CLIP
1 REAR TAILGATE TOYOTA LOGO
1 REAR TAILGATE WORDING 'PRIUS'
1 REAR TAILGATE WORDING 'HYBRID'
1 REAR TAILGATE STICKER 'TRANS-CAB'
1 REAR TAILGATE STICKER '6555-3333'
1 REAR BUMPER RETAINER CLIP

\$	sn	700.00	X
\$	n	90.00	75% ✓
\$	nn	47.90	
\$	nn	54.60	
\$	nn	54.60	
\$	nn	80.00	
\$	nn	80.00	
\$	nn	65.00	

AAD2010-019

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9500Z

1SET TAILLAMP CLIP

- 1 Rear Licence Plate with Holder
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 WINDSCREEN MOULDING

\$	nn	60.00	}	X
\$	nn	130.00		
\$	nn	150.00		
\$	nn	130.00		
\$	nn	200.00		
TOTAL	\$	1,842.10		

TOTAL PARTS	\$	6,474.70
--------------------	----	-----------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

Putty And Spray Painting Of The Affected Portion.

\$		1,200.00	200
----	--	----------	-----

To reinstall rear bumper parking sensor.

\$		170.00	50
----	--	--------	----

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	nn	250.00	X
----	----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		1,200.00	200
----	--	----------	-----

To Check Electrical Lighting Concerned.

\$		170.00	100
----	--	--------	-----

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$	nn	300.00	X
----	----	--------	---

TOTAL	\$	3,460.00
--------------	----	-----------------

Over All Total	\$	9,934.70
-----------------------	----	-----------------

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

15 Days

2 days