



# MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

## Estimation

Date:

Vehicle:

Make / Model:

Chassis No:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

6/10/2020

Acknowledged by Repairer

SMR3784C

TOYOTA PRIUS

| No.                 | Description                                    | Unit | Unit Price               | Amount      |
|---------------------|------------------------------------------------|------|--------------------------|-------------|
|                     | Parts Replacement:                             |      |                          |             |
| 1                   | REAR BUMPER <i>/ det.</i>                      | 1    | \$ 698.00                | \$ 698.00   |
| 2                   | REAR BUMPER LOWER <i>X / SCR</i>               | 1    | \$ 412.00                | \$ 412.00   |
| 3                   | REAR BUMPER SIDE RETAINER <i>X Svc</i>         | 2    | \$ 112.00                | \$ 224.00   |
| 4                   | TAILAMP LH <i>X Svc</i>                        | 1    | \$ 489.00                | \$ 489.00   |
| 5                   | REAR FENDER LH <i>/ det</i>                    | 1    | \$ 798.00                | \$ 798.00   |
| 6                   | REAR FENDER COWLING LH <i>X Svc</i>            | 1    | \$ 159.00                | \$ 159.00   |
| 7                   | REAR FENDER QUARTER GLASS MLDG LH <i>/ Nec</i> | 1    | \$ 189.00                | \$ 189.00   |
| 8                   | ROCKER PANEL GARNISH LH <i>/ det</i>           | 1    | \$ 798.00                | \$ 798.00   |
| 9                   | REAR DOOR LH <i>/ det</i>                      | 1    | \$ 1,214.00              | \$ 1,214.00 |
| 10                  | REAR OUTER MOULDING LH <i>X Svc</i>            | 1    | \$ 124.00                | \$ 124.00   |
| 11                  | REAR DOOR WEATHERSTRIP LH <i>X Svc</i>         | 1    | \$ 198.00                | \$ 198.00   |
| 12                  | REAR KNUCKLE ARM LH <i>X Svc</i>               | 1    | \$ 487.00                | \$ 487.00   |
| 13                  | REAR KNUCKLE ARM BEARING LH <i>X / Jam</i>     | 1    | \$ 148.00                | \$ 148.00   |
| 14                  | REAR AXLE <i>X Svc</i>                         | 1    | \$ 1,985.00              | \$ 1,985.00 |
| 15                  | REAR SHOCK ABSORBER LH <i>X Svc</i>            | 1    | \$ 418.50                | \$ 418.50   |
|                     |                                                |      |                          | \$ 8,341.50 |
|                     |                                                |      | Less 25%                 | \$ 2,085.38 |
|                     |                                                |      | Total                    | \$ 6,256.13 |
|                     | S/Nett items:                                  |      |                          |             |
| 1                   | REAR BUMPER CLIPS SET <i>/ Nec</i>             | 1    | \$ 50.00                 | \$ 50.00    |
| 2                   | REAR FENDER COWLING CLIPS SET <i>X</i>         | 1    | \$ 50.00                 | \$ 50.00    |
| 3                   | REAR SPORTS RIM RH <i>/ SCR</i>                | 1    | \$ 800.00                | \$ 800.00   |
| 4                   | REAR TYRE RH <i>X</i>                          | 1    | \$ 250.00                | \$ 250.00   |
| 5                   | REAR STICKER SET <i>X</i>                      | 1    | \$ 300.00                | \$ 300.00   |
| 6                   | BRAKE FLUID <i>X</i>                           | 1    | \$ 50.00                 | \$ 50.00    |
|                     |                                                |      |                          | \$ 1,500.00 |
|                     | Labour to:                                     |      |                          |             |
| 1                   | TO CHECK ELECTRICAL WIRING                     | 1    | \$ 80.00                 | \$ 80.00    |
| 2                   | REMOVE AND TRANSFER REVERSE SENSOR             | 1    | \$ 120.00                | \$ 120.00   |
| 3                   | CONDUCT FULL WHEEL ALIGNMENT                   | 1    | \$ 120.00                | \$ 120.00   |
| 4                   | REMOVE AND REFIT REAR UNDERCARRIAGE            | 1    | \$ 400.00                | \$ 400.00   |
| 5                   | TO RESPRAY UNDERCOATING                        | 1    | \$ 150.00                | \$ 150.00   |
| 6                   | APPLY ANTI RUST ON AFFECTED AREAS              | 1    | \$ 200.00                | \$ 200.00   |
| 7                   | SPRAY PAINTING ON AFFECTED AREAS               | 1    | \$ 1,000.00              | \$ 1,000.00 |
| 8                   | PANEL BEATING ON AFFECTED AREAS                | 1    | \$ 1,000.00              | \$ 1,000.00 |
|                     |                                                |      |                          | \$ 3,070.00 |
| Repair day - 4 days |                                                |      | Parts Replacement Amount | \$ 7,756.13 |
|                     |                                                |      | Total Amount for Labour  | \$ 3,070.00 |

LIS

After paint photo

Sun Pin (LH)

07/10/2020

TP with prejudice

Resurvey

06/10/2020

30

30

60

X

30

30

600

800