

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0742/2020/NS
DATE	:	7-Oct-20
WIP	:	52224

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.**YOUR INSURED VEH NO : SGC 5802 X****AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME	:	MR LIM YUAN SZE, DERRICK
ADDRESS	:	BLK 343 CHO CHU KANG AVENUE 3 #18-26 SINGAPORE 689343
TELEPHONE	:	HP +65 98342369
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	MP313068
VEHICLE NO	:	SLQ 5163 Z
MODEL CODE	:	AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR	:	13/7/2017
ENGINE NO	:	CVN 040731
CHASSIS NO	:	WAUZZZF47HA176638
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	6-Oct-20
PLACE OF ACCIDENT	:	MANDAI ROAD



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 5163 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00 ✓	
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 480.00 ?	
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,000.00	1000 Without End Panel 2250 With End Panel.
5	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING. ?	\$ 2,850.00	1650.
6	TO CARRY OUT PAINT COATING FOR AFFECTED PANELS.	S/N \$ 200.00 ✓	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 7,362.00</u>	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 5163 Z

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>Dislocated</i>		\$ 2,181.00	✓
2 REAR BUMPER FIXING PARTS <i>new</i>		\$ 72.00	x
3 REAR BUMPER SECURING STRIP <i>?</i>		\$ 220.00	?
4 REAR BUMPER SPOILER <i>Rehanded</i>		\$ 246.00	✓
5 REAR LIGHT REFLECTOR - LH / RH <i>RH cracked</i>	2	\$ 82.00	41
6 LED LICENSE PLAT LIGHT <i>new</i>	2	\$ 197.00	x
7 LED TAIL LIGHT - LH / RH <i>?</i>	2	\$ 2,016.00	?
8 TAIL LIGHT TRIM - LH / RH <i>?</i>	2	\$ 60.00	?
9 REAR BUMPER CARRIER <i>Best.</i>		\$ 886.00	✓
10 REAR BUMPER CARRIER SEAL <i>?</i>	2	\$ 28.00	?
11 REAR BUMPER GUIDE SECTION - LH / RH <i>new 2</i>	2	\$ 44.00	x
12 REAR PARKING AID SENSOR - INNER / OUTER <i>1 piece dnd</i>	2	\$ 484.00	242.
13 REAR PARKING AID SEAL RING <i>new</i>	4	\$ 14.00	✓
14 REAR BUMPER WIRING SET <i>Not a</i>		\$ 664.00	x
15 BOOT LID CONTROL UNIT <i>?</i>		\$ 399.00	?
16 REAR LID <i>Dented</i>		\$ 2,623.00	✓
17 REAR LID HINGE - LH / RH <i>new</i>	2	\$ 452.00	x
18 REAR LID LOCK <i>?</i>		\$ 227.00	?
19 REAR LID ATTACHMENT PARTS <i>new</i>		\$ 406.00	x
20 LID LOCK PUSH BUTTON <i>Not a</i>		\$ 515.00	x
SUB TOTAL SPARE PARTS	:	\$ 11,816.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 5163 Z

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 REAR LID LOCK STRIKER <i>Neu</i>		\$ 33.00	✓
22 REAR LID FLAP GASKET <i>Neu ?</i>		\$ 203.00	?
23 PACKING ADHESIVE <i>Neu</i>		\$ 18.00	✓
24 AUDI EMBLEM		\$ 122.00	✓
25 A4 INSCRIPTION		\$ 95.00	✓
26 TFSI INSCRIPTION		\$ 95.00	✓
27 REAR CROSS PANEL ?		\$ 257.00	?
28 CROSS PANEL REINFORCEMENT ?		\$ 499.00	?
29 REAR CROSS PANEL TRIM <i>Del d</i>		\$ 164.00	✓
30 REAR LID TRIM PANEL ?		\$ 325.00	?
31 STONE CHIP ?	S/N	\$ 180.00	?
32 CAVITY WAX ?	S/N	\$ 140.00	?
33 ACRYLIC SEALANT ?	S/N	\$ 180.00	?
34 REAR NO PLATE <i>Bent</i>	S/N	\$ 60.00	✓
35 SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 14,487.00	
TOTAL LABOUR CHARGES	:	\$ 7,362.00	
GRAND TOTAL	:	\$ 21,849.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *08/10/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 days without end panel replacement
09 days with end panel replacement*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT