

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0705/2020/NS
DATE : 29-Sep-20
WIP : 51095

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SJX 9541 B

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR SIA CHEE POH(XIE ZHIBAO)
ADDRESS : BLK 267B COMPASSVALE LINK
#15-55
SINGAPORE 542267
TELEPHONE : HP +65 81807500
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100500841-03
VEHICLE NO : **SLL 1307 D**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 14/2/2017
ENGINE NO : CHZ 158654
CHASSIS NO : WAUZZZ8V4H1028226
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Sep-20
PLACE OF ACCIDENT : PIE TOWARDS TUAS

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1307 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00	
3	TO RENEW REAR WINDSCREEN AND RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS REAR 1/4 GLASS.	S/N \$ 400.00	
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	
SUB TOTAL LABOUR CHARGES		: <u>\$ 1,760.00</u>	

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1307 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	
8	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD RHS REAR FENDER AND REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,700.00	
9	TO RESPRAY REAR BUMPER, REAR LID, HINGES, RHS REAR FENDER, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 5,650.00	
10	TO RENEW REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$ 480.00	
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 18,582.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1307 D

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER		\$ 1,944.00	
2	REAR BUMPER FIXING PARTS		\$ 191.00	
3	WHEEL HOUSNG LINER ADAPTER - RH		\$ 37.00	
4	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 32.00	
5	REAR BUMPER LOCKING MECHANISM	2	\$ 59.00	
6	REAR BUMPER SPOILER		\$ 234.00	
7	REAR LIGHT REFLECTOR - RH		\$ 41.00	
8	LED TAIL LIGHT - RH OUTER		\$ 867.00	
9	TAIL LIGHT TRIM - RH		\$ 30.00	
10	LED TAIL LIGHT - RH INNER		\$ 867.00	
11	TAIL LIGHT TRIM - RH		\$ 30.00	
12	REAR REINFORCEMENT BEAM		\$ 565.00	
13	REAR BUMPER BRACKET - LH		\$ 27.00	
14	REAR BUMPER BRACKET - RH		\$ 28.00	
15	REAR BUMPER GUIDE SECTION - RH		\$ 66.00	
16	REAR PARKING AID SENSOR - INNER / OUTER	3		TBC
17	REAR PARKING AID SEAL RING	4	\$ 14.00	
18	REAR LID		\$ 2,564.00	
19	REAR LID ATTACHMENT PARTS		\$ 291.00	
20	REAR LID HINGE - LH / RH	2	\$ 506.00	
SUB TOTAL SPARE PARTS		:	\$ 8,393.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1307 D

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR LID FLAP GASKET		\$ 203.00	
22	REAR FENDER - RH		\$ 2,305.00	
23	REAR WINDSCREEN		\$ 805.00	
24	SIDE WINDOW - RH		\$ 563.00	
25	PRIMER		\$ 19.00	
26	REAR CROSS PANEL		\$ 356.00	
27	CROSS PANEL REINFORCEMENT		\$ 725.00	
28	CONNECTING PLATE - RH		\$ 143.00	
29	REAR SILENCER		\$ 712.00	
30	REAR SILENCER DUAL CLIP		\$ 57.00	
31	EXHAUST SYSTEM RETAINER	2	\$ 79.00	
32	REAR SILENCER HEAT SHIELD		\$ 158.00	
33	PACKING ADHESIVE		\$ 18.00	
34	AUDI EMBLEM		\$ 122.00	
35	A3 INSCRIPTION		\$ 95.00	
36	TFSI INSCRIPTION		\$ 95.00	
37	WHEEL HOUSING LINER		\$ 237.00	
38	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00	
39	REAR NO PLATE	S/N	\$ 60.00	
40	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
SUB TOTAL SPARE PARTS		:	\$ 7,040.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1307 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 1/4 GLASS SEALANT	S/N	\$ 100.00	
42 METAL FILLER POWDER	S/N	\$ 280.00	
43 STONE CHIP	S/N	\$ 180.00	
44 CAVITY WAX	S/N	\$ 140.00	
45 ACRYLIC SELANT	S/N	\$ 180.00	
46 SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS	:	\$ 16,663.00	
TOTAL LABOUR CHARGES	:	\$ 18,582.00	
GRAND TOTAL	:	\$ 35,245.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT