

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0721/2020/NS
DATE : 1-Oct-20
WIP : 51581

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMP 7695 K

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS RENUGADEVI D/O MANICKAM
ADDRESS : 32 PAVILLION GREEN
SINGAPORE 658317
TELEPHONE : HP +65 91772771
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800035588-01
VEHICLE NO : **SLX 7015 T**
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 6/4/2018
ENGINE NO : CVK 056254
CHASSIS NO : WAUZZZF58JA075557
MILEAGE : 31698KM
DATE IN : 1-Oct-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Oct-20
PLACE OF ACCIDENT : TURF CITY GALLOP HILL RESORT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 7015 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND RFGAS.	S/N \$ 1,400.00	
4	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 400.00	
5	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY.	S/N \$ 1,800.00	
SUB TOTAL LABOUR CHARGES		: \$ 4,480.00	

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 7015 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	
7	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS FRONT DOOR.	\$ 4,000.00	
8	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	
9	TO TOW VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	
10	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N \$ 384.00	
TOTAL LABOUR CHARGES		: \$ 14,224.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 7015 T

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER		\$ 2,251.00	
2 FRONT BUMPER FIXING PARTS		\$ 402.00	
3 FRONT BUMPER SECURING STRIP	2	\$ 70.00	
4 FRONT BUMPER GRILLE - CENTRE		\$ 194.00	
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 225.00	
6 FRONT BUMPER SPOILER		\$ 529.00	
7 FRONT BUMPER AIR GUIDE - RH		\$ 62.00	
8 RADIATOR GRILLE		\$ 2,300.00	
9 ULTRASOUND SENSOR SUPPORT - LH / RH	2	\$ 102.00	
10 RADIATOR GRILLE COVER - UPPER		\$ 187.00	
11 FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 468.00	
12 FRONT BUMPER GUIDE SECTION - RH		\$ 36.00	
13 FRONT PARKING AID SENSOR - OUTER			TBC
14 FRONT PARKING AID SEAL RING	4	\$ 14.00	
15 HORN - RH LOW TONE		\$ 124.00	
16 SPRING SHACKLE - RH		\$ 29.00	
17 FRONT FENDER - RH		\$ 1,048.00	
18 FRONT FENDER ATTACMENT PARTS		\$ 53.00	
19 FRONT FENDER CLOSING ELEMENT - RH		\$ 73.00	
20 FRONT FENDER BRACKET - INNER		\$ 35.00	
SUB TOTAL SPARE PARTS	:	\$ 8,202.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 7015 T

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT FENDER BRACKET - CENTRE	\$	57.00	
22 FRONT FENDER BRACKET - OUTER	\$	35.00	
23 FRONT FENDER BRACE - RH	\$	117.00	
24 DEFORMATION ELEMENT BRACKET - RH	\$	49.00	
25 WHEEL HOUSING LINER - RH	\$	272.00	
26 WHEEL SPOILER	\$	73.00	
27 WHEEL SPOILER TRIM - RH	\$	36.00	
28 STONE CHIP GUARD - RH	\$	50.00	
29 FRONT FENDER TRIM BRACKET	\$	24.00	
30 BONNET IMPACT PROTECTION - CENTRE	\$	27.00	
31 BONNET IMPACT PROTECTION - LH	\$	28.00	
32 BONNET IMPACT PROTECTION - RH	\$	27.00	
33 FENDER TOP LEDGE COVER - UPPER	\$	35.00	
34 FENDER TOP LEDGE COVER - LOWER	\$	16.00	
35 LED HEADLIGHT - RH	\$	7,812.00	
36 MAIN LIGHT ELECTRONICS POWER MODULE	\$	749.00	
37 LIGHT CONTROL SYSTEM CONTROL UNIT	\$	742.00	
38 LED WITH HEAT SINK - RH	\$	1,140.00	
39 HEADLIGHT HOSE	\$	36.00	
40 HEADLAMP REPAIR KIT - RH	\$	130.00	
SUB TOTAL SPARE PARTS	:	\$ 11,455.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 7015 T

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 HEADLIGHT COMPENSATING PIECE	\$	40.00	
42 HEADLIGHT COMPENSATING PIECE	\$	40.00	
43 LIFT CYLINDER - RH	\$	196.00	
44 LIFT CYLINDER CORRUGATED PIPE	\$	85.00	
45 FRONT FENDER TRIM - RH	\$	157.00	
46 FRONT DOOR TRIM - RH	\$	157.00	
47 LOCK CARRIER	\$	1,004.00	
48 READY MIX COOLANT	\$	91.00	
49 FRONT ALUMINIUM RIM - RH	\$	1,012.00	
50 LOWER CONTROL ARM - RH	\$	533.00	
51 FRONT SUSPENSION GUIDE - RH	\$	932.00	
52 UPPER CONTROL ARM - RH FRONT	\$	506.00	
53 UPPER CONTROL ARM - RH REAR	\$	506.00	
54 WHEEL BEARING HOUSING - RH	\$	957.00	
55 SWIVEL JOINT	\$	191.00	
56 WHEEL HUB	\$	465.00	
57 DOUBLE ANGLED BALL BEARING	\$	239.00	
58 SUSPENSION FORKS - RH	\$	261.00	
59 COUPLING ROD	\$	127.00	
60 ANTI ROLL BAR	\$	428.00	
SUB TOTAL SPARE PARTS	:	\$ 7,927.00	



TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 7015 T

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	DRIVE SHAFT		\$	2,620.00
62	GAS SHOCK ABSORBER		\$	289.00
63	TRACK ROD		\$	98.00
64	TIE ROD END - RH		\$	195.00
65	FRONT NO PLATE	S/N	\$	60.00
66	SUNDRIES		\$	400.00
TOTAL SPARE PARTS		:	\$	31,246.00
TOTAL LABOUR CHARGES		:	\$	14,224.00
GRAND TOTAL		:	\$	45,470.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT