

Section A - Accident Details

Registration Number	SHC4130X
Case Reference Number	TAX/10/20/2008
Registration Date	12/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HO KWONG MENG
Type of Accident	Side Swipe
Accident Date and Time	5/10/2020 2:05 PM
Accident Reported Date and Time	5/10/2020 3:28 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108385
Special Instruction to ARC, if any	RIGHT PORTION
Prepared Date and Time	6/10/2020 9:07 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845 00	\$500 00
Total Spray Cost	\$2,970 00	\$1,150.00
Total Spare Part Cost	\$15,819.88	\$600.23
Total Other Cost	\$720 00	\$80 00
TOTAL COST	\$20,354.88	\$2,330.24 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / III
ARC / Surveyor Sign Off Date	06/10/2020 9:33 AM	07/10/2020 3:35 PM
Signature		
Remarks		P/P, before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2010-0329	Invoice Number	
Quotation Date	23 10 2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$500.00
Total Labour	\$845.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPRAY FRONT PILLAR RH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$360.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,970.00	\$1,150.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$720.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	NEC
		6101347010	PILLAR, FRONT BODY, RH	0.00	\$339.40	0.00	\$0.00	Replace	Not Given	SVC
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	
		5382747050	PROTECTOR, FR FENDER RH	0.00	\$90.40	0.00	\$0.00	Replace	Not Given	SVC
		5385147061	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	SVC
		5387547070	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given	SVC
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	NEC
		5380147080	FENDER SUB-ASSY, FR. RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 23/10/2020

User ID : PohSuan

81145476 91	UNIT , HEADLAMP , RH	0.00	\$2,558.90	0.00	\$0.00	Replace	Not Given	X	SVC
81210470 20	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given	X	SVC
51447470 30	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Not Given	X	SVC
51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Not Given	X	SVC
51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X	SVC
76085479 16	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	Replace	Not Given	X	SVC
43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X	SVC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X	SVC
65637470 60	LINER, REAR FENDER , RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X	SVC
65565470 10	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$33.70	0.00	\$0.00	Replace	Not Given	X	SVC
61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	✓	
82153472 50	WIRE, REAR DOOR, RH	0.00	\$206.70	0.00	\$0.00	Replace	Not Given	X	SVC
68630470 50	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given	X	SVC
68770520 31	HINGE ASSY, REAR DOOR , LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given	X	SVC
68750201 22	HINGE ASSY, REAR DOOR , UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given	X	SVC
67003472 10	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair	✓	
82152475 51	WIRE, FRONT DOOR, LH	0.00	\$445.70	0.00	\$0.00	Replace	Not Given	X	SVC
68730121 20	HINGE ASSY, FRONT DOOR , LOWER RH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given	X	SVC
68710121 51	HINGE ASSY, FRONT DOOR , UPPER RH	0.00	\$82.10	0.00	\$0.00	Replace	Not Given	X	SVC
68610470 40	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given	X	SVC
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓	NEC
67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair	✓	
87915470 70A1	COVER, OUTER MIRROR, RH	0.00	\$89.50	0.00	\$0.00	Replace	Not Given	X	SVC
87910474 50	MIRROR ASSY, OUTER REAR VIEW , RH	0.00	\$1,373.50	0.00	\$0.00	Replace	Not Given	X	SVC
75850479 10	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$576.00	100.00	\$0.00	Replace	Repair	✓	
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X	SVC
52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	✓	NEC
53101470 80	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Not Given	X	SVC
53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given	X	SVC
52114471 90	BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Not Given	X	SVC
52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given	X	SVC
52115470 50	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	✓	BR
52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace	✓	CRU
Total			\$19,856.18		\$600.24				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

600.24 /
500.00 /
+1230.00 /
2330.24 /
5 days