

Lee Kuan Hwa Motor Service (Co.Reg.No:36463500B)

20 Gul Crescent
Singapore 629529
Tel: 62699192 Fax: 62692239 Email: kuanhwa@singnet.com.sg

INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MU013224	Date of Loss:	30/09/2020
Vehicle Reg. No.:	XE3905J	Driveable?	YES
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	TANGLIN CORPORATION PTE LTD		
Driver:	YONG CHEE FUI GREGORY		
Make/Model:	MAN TGS 35.360, 10.5 D 8X4 BB (M)	Vehicle Reg. Date:	26/12/2017
Vehicle Colour:	White	Gen Condition:	Good
Engine No:	50546182524618	Chassis No:	WMA37SZZ0HM729564
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Description of Accident/Loss: REFER TO ATTACHED STATEMENT
Present Location: LEE KUAN HWA MOTOR SERVICE (GUL CRESCENT)

COST OF CLAIMS	Amount
Parts	9,901.36
Miscellaneous Items	641.85
Labour	3,000.00
Paintwork Labour	0.00
Towing	0.00

Nett Amount (S\$) **13,542.44** ~~13,543.21~~

This claim is handled by: **ADELINE LEE SU FANG**

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Oct 2020)
 Parts: N/A MAN TGS 35.360 10.5 D 8X4 BB (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lee Kuan Hwa Motor Service/XE3905J/26/10/2020 17:26
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*ADAPTER			
2	1		*COVER PLATE	0.00	0.00	*11.76 F ?
3	1		*EQUIPMENT HOLDER	0.00	0.00	*12.12 F ?
4	1		*TOOL SUPPORT	0.00	0.00	*48.68 F ?
5	1		*CABLE HARNESS MANUAL GEARBOX	0.00	0.00	*25.88 F ?
6	1		*CABLE HARNESS EBS-5	0.00	0.00	*143.14 F ?
7	1		*CABLE HARNESS SYSTEM CARRIER	0.00	0.00	*440.62 F ?
8	1		*ELECTRONIC CONTROL UNIT PTM	0.00	0.00	*1,619.92 F ?
9	1		*ELECTRONIC CONTROL UNIT	0.00	0.00	*1,025.98 F ?
10	1		*TRIM	0.00	0.00	*4,017.34 F /BNT
11	1		*INSTR.PANEL CTR PART	0.00	0.00	*23.70 F /BNT
12	1		*CARRIER CENTRE ART	0.00	0.00	*73.70 F /BNT
13	1		*INSTRUMENT PANEL	0.00	0.00	*71.26 F /BNT
14	1		*HOUSING BOTTOM PART	0.00	0.00	*775.84 F /BNT
15	1		*HOUSING UPPER PART	0.00	0.00	*137.20 F /BNT
16	2		*AIR DUCT	0.00	0.00	*345.58 F /BNT
17	1		*AIR DUCT	0.00	0.00	*6.36 F ?
18	1		*AIR OUTLET	0.00	0.00	*29.52 F ?
19	1		*SEALING STRIP	0.00	0.00	*107.50 F /BNT
20	1		*PACKING NARROW	0.00	0.00	*11.62 F /NEC
21	1		*PACKING	0.00	0.00	*45.62 F /BNT
				0.00	0.00	*27.90 F /BNT
Sub Total (S\$)						9,001.24
+ Margin on L,N Items 10.00% (S\$)						900.12
Total Parts (S\$)						9,901.36

F=Franchise part.

Lee Kuan Hwa Motor Service/XE3905J/26/10/2020 17:26. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	7% GST FROM SUPPLIER	630.08
2	1	OD/TP Case (Insurer)	11.00 11.77
Sub Total (S\$)			641.85

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR FOR REMOVE, INSTALL AND TROUBLESHOOT WIRE HARNESS OF CABIN DASHBOARD, REPLACE PTM AND EBS CONTROL UNIT AND THE FOLLOWING PARTS AND DO-UP SYSTEM REPROGRAM	New	3,000.00
Gross Labour Cost (S\$)			3,000.00

Lee Kuan Hwa Motor Service/XE3905J/26/10/2020 17:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA2 LKIC

28/10/2020 1030

Part by Part Repair

30 days (including check items)

check item photos

Before paint photos