

Customer: NAZ REF: TMI

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
Type: M/Car / M/Cycle / BUS / Van / Truck / Taxi / Prime Mover /
Truck / Trailer or _____
To inspect Vehicle No: _____
Colour: WHITE WITTE
Sp Reading: NA - Cylind affected T/Radio: Insured
Eng/No: _____
Chassis: WMA375220HM729564
Gen. Cond. Good / Fair / Poor / Burnt
Steering: In order / Jammed / Locked / Burnt or
Brake: In order / Jammed / Locked / Burnt or
Wash: Wash / SIRIM / STD / ARIN or
Tyre Size: F: 315 / 80 R22.5
R: 11

US / DUT / EXH / OVA / GY / ES / I / ZA / M / C / I / O / I / S / U / P / I / R / S / U / I /
TOYO / YOKO or CONTINENTAL (F) HANKOOK (M) HYFLY (R)
Front: 4 mm 6 mm
Rear: 4 mm 6 mm
D.O.A. 30/9/2020 28 07/10/2020
Survey held at ST Engineering Land Systems
Des. of Damages: Frl / Rear / DIS / HIS / UIC / Noelap or
Interior burnt
The UIC / Chassis frame / Body structure affected due to damage.

COF Rebate: \$30 291.00
Repair Unit: \$60K

10.02.2021 2.53PM CONFIRMED FINAL FIG \$25,363.78 ; 30 DAYS WITH SIEW CHEN.
(Red \$381.38; 1%)

Days Of Repair: 30
Resurvey No. of Trip: 2
Survey Fee: _____
Transportation: _____
Add Fee: ☐ Site Insp / \$ _____
☐ Interview / \$ _____
☐ Tech. Invo / \$ _____
☐ Weekend / \$ _____
MER-OD
25363.78