



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LOH AI LIN Reg No/Reg Date SMJ2534G*KC17/ 27/02/201 Date In/Mileage / 14576 Chassis No KNAF3416MK5030251 Engine No G4FGJH719801 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/10/2020/ 09:53	QUE	261 / Edwin Caina	22283			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800 2000.00
RENEW FRT BUMPER,BONNET & FRT SUPPORT								
REPAIR LHF FENDER & RHF FENDER								
E PNT98000								700 1400.00
RESPRAY FRT BUMPER,BONNET,LHF FENDER & RHF FENDER								
E PNT88000								? 100.00
REMOVE & REFIT AC COND & RADIATOR								? 80.00
M SUNDRY								
TOP UP AIRCON GAS								✓ 30.00
A 54900099								✓ 120.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								bt ✓ 50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								20 30.00
M SUNDRY								
SUPPLY FRT NUMBER PLATE WITH CASING								
M SUNDRY								
Sundries								bt 1201.60
M	PANEL ASSY-HOOD			1.00	1502.00	20.00		? 34.40
M	HINGE ASSY-HOOD,LH			1.00	43.00	20.00		? 34.40
M	HINGE ASSY-HOOD,RH			1.00	43.00	20.00		? 10.40
M	CLIP-HOOD INSULATING PAD MTG			13.00	1.00	20.00		? 82.40
M	LATCH ASSY-HOOD			1.00	103.00	20.00		de 209.60
M	GRILLE-FRONT BUMPER			1.00	262.00	20.00		de 506.40
M	COVER-FR BUMPER			1.00	633.00	20.00		en 262.40
M	GRILLE ASSY-RADIATOR			1.00	328.00	20.00		? 67.20
M	ABSORBER-FRONT BUMPER ENERGY			1.00	84.00	20.00		? 91.20
M	STIFFNER-FR BPR LWR			1.00	114.00	20.00		? 17.60
M	BRACKET-FR BUMPER UPR SIDE MTG			1.00	22.00	20.00		? 17.60
M	BRACKET-FR BUMPER UPR SIDE MTG			1.00	22.00	20.00		? 25.60
M	ORNAMENT-KIA NO.115			1.00	32.00	20.00		? 28.80
M	MOULDING-FRONT BUMPER,LH			1.00	36.00	20.00		? 975.20
M	LAMP ASSY-HEAD,LH			1.00	1219.00	20.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LOH AI LIN Reg No/Reg Date SMJ2534G*KC17/ 27/02/201 Date In/Mileage / 14576 Chassis No KNAF3416MK5030251 Engine No G4FGJH719801 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/10/2020/ 09:53	QUE	261 / Edwin Caina	22283			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BEAM COMPLETE-FR BUMPER				1.00	497.00	20.00	? 397.60
M	CARRIER ASSY-FRONT END MODULE				1.00	675.00	20.00	? 540.00
M	COOLANT (4L)				1.00	26.00	23.00	? 20.02

Estimate

SURVEYOR NAME : Tanpin 97495749SURVEYOR SIGNATURE : [Signature]DATE : 7/10/20 @ 2:45 pm

REMARKS : Not Authorise, Resurvey
ex! to be advise Resurvey before paint
tanpin @ 5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirm & accepted by
 • Third party survey is on a "Without Prejudice" basis
 • No legal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Authorized signatory and company stamp

7% GST on	Nett	8,332.42
	8332.42	583.27
	Total Payable	8,915.69

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.