

EVER SEN AUTO SERVICE

BLK 3022A UBI ROAD 1 #01-49

SINGAPORE 408716

Tel No. : 67437111 Fax No. : 67489611

E-Mail : eversenauto@singnet.com.sg

Buss. Reg. No. : B24044500/K

JTHTo2P20014+936

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD **Supplementary Estimate : TI20/013**

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221003

Aline

Date : 06/10/2020

Vehicle Num. : GBD2345 Y

Make/Model : TOYOTA HIACE

Chassis/Eng# :

Accident Date : 06/10/2020

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	set	Body panel right rear <i>Defect</i>		
		SEALANT <i>Ner</i>		
		List Total S\$:		
		LABOUR :		
		ACCIDENT REPAIR PANEL BEATING		
		RESpray PAINT WORK ON REPAIR AREA		
		RUSTPROOFING TREATMENT		
		Labour Total S\$:		

1718

~~2067.10~~
120.00 *60*

1778

1333.50

750

2,187.10

~~850.00~~ *400*

~~800.00~~ *300*

~~100.00~~ *50*

1,750.00

SingDollars : Three Thousand Nine Hundred Thirty-Seven & Cents Ten Only

Total S\$: 3,937.10

EVER SEN AUTO SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature :

Date :

Total: 2083.50

2/S: 1650.

Adrian Lj

2/S 09/10/20

04 Days