



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



| | | | | |
|--|--|-----------------|--------------------|---|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20010812/Evd3e2 | | | | |
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: 20-10-2020 |  |
| Code: INC4 | | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | FBP 3998T | Veh. Inspected | SHC 2059H | |
| Policy No. | 5108470092-01 | Coverage (\$) | 0.00 | |
| Claim No. | MT/1106243-001 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 07/10/2020 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI I40 | c.c | 1685 | |
| Engine No. | HIDDEN | Year of Reg. | 2017 | |
| Chassis No. | KMHLB41UMHU098646 | Colour | BLUE | |
| Odometer | 383629 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 205/60 R16 | FIRESTONE | 5 mm | |
| L/H Front Tyre | 205/60 R16 | FIRESTONE | 5 mm | |
| R/H Rear Tyre | 205/60 R16 | FIRESTONE | 5 mm | |
| L/H Rear Tyre | 205/60 R16 | FIRESTONE | 5 mm | |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| Accident Date | 03/10/2020 | Inspection Date | 07/10/2020 | |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | |