

OMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2059H
MAKE : HYUNDAI
MODEL : i40

DATE: 7. Oct. 2020

LWY

DOA: 3. Oct. 2020

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper / DD			\$1,106.00
10	Rear Bumper Clips / MC		\$2.20	\$22.00
1	Rear Bumper Side Bracket - LH / BR			\$35.60
1	Rear Bumper Reinforcement X N/M			\$428.40
1	Rear Bumper Reinforcement Bracket LH X N/M			\$80.30
1	Rear Bumper Undercover X N/M			\$228.00
1	Rear Bumper Reflector - LH / CHT			\$32.00
SUB TOTAL				\$1,932.30
LESS 20%				\$386.46
DISCOUNTED TOTAL				\$1,545.84
1	Rear Bumper Rubber Mat / MC			\$50.00
1	Rear Bumper Advertisement sticker / MC			\$50.00
1	Rear Left Fender Advertisement sticker / MC			\$100.00
1	Rear Bumper Reverse Sensor X N/M			\$135.70
Less 10%				
200				
Labour Charge				\$335.70
1	Panel Beating		280	\$300.00
1	Spray Painting Charge		200	\$250.00
1	Wiring Charge		30	\$50.00
1	Remove/refix Reverse Sensor		30	\$100.00
TOTAL LABOUR				\$700.00
ESTIMATE TOTAL				\$2,581.54
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Steve (LKK)

Wm Profr
7/10/20, 2.30pm

2 days

L/S

Ry PL spy

P- 956.48

M- 200

L- 540

1696.48

L/S- 1357.18
= 1350