

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Phoebe Xie

Date: 16 Oct 2020

Preliminary AdviceVehicle No : SFJ8666C
Make : MERCEDES-BENZ GLA180
Assignment Date : 07/10/2020
Date of Inspection : 08/10/2020
Inspection At : UNIMOTOR CO (HQ)
NO 1 KAKI BUKIT AVE 6 #01-94
SINGAPORE 417883Accident Date : 06/10/2020
Policy No. : DMPG20007161
Excess : S\$0.00
Est. Duration of Repair : 4**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,302.06	(ESTIMATE \$8,300.45 + SUPPLEMENTARY \$161.00)
Revised Amount	:S\$	6,128.95	(INCLUSIVE OF SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	6,128.95	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000.00
COE / PARF Rebate	:S\$	53,069.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,931.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.