

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 08 Oct 2020

Preliminary Advice

Vehicle No	: SFJ8666C	Accident Date	: 06/10/2020
Make	: MERCEDES-BENZ GLA180	Policy No.	: DMPG20007161
Assignment Date	: 07/10/2020	Excess	: S\$0.00
Date of Inspection	: 08/10/2020	Est. Duration of Repair	: 4
Inspection At	: UNIMOTOR CO (HQ) NO 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,300.45
Revised Amount	:S\$	6,502.70
Check Items (Estimated)	:S\$	408.25
Total	:S\$	6,910.95

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000.00
COE / PARF Rebate	:S\$	53,069.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,931.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ADVISE ON EXCESS AND AUTHORISATION.
THE VEHICLE REPAIR ON PART BY PART BASIS.