

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SLU3553Z

OUR REF.: SMR2770Z

TO: MSIG Insurance (Singapore) Pte Ltd

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.: SMR2770Z

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAILGATE		1	\$ 7,000.00
2	TAILGATE WEATHERSTRIP		1	\$ 500.00
3	TAILGATE MERCEDES LOGO		1	\$ 150.00
4	TAILGATE EMBLEM "GLE 400"		1	\$ 120.00
5	TAILGATE EMBLEM "4MATIC"		1	\$ 120.00
6	TAILGATE LAMP LH		1	\$ 700.00
7	TAILGATE LAMP RH		1	\$ 700.00
8	TAILLAMP LH		1	\$ 900.00
9	TAILLAMP RH		1	\$ 900.00
10	REAR BUMPER		1	\$ 2,500.00
11	REAR BUMPER SPONGE		1	\$ 250.00
12	REAR BUMPER RETAINER LH		1	\$ 95.00
13	REAR BUMPER RETAINER RH		1	\$ 95.00
14	REAR BUMPER TOWING COVER		1	\$ 200.00
15	REAR BUMPER LOWER COVER TRIM		1	\$ 800.00
16	REAR BUMPER DIFFUSER CHROME		1	\$ 800.00
17	REAR BUMPER REFLECTOR LH		1	\$ 50.00
18	REAR BUMPER REFLECTOR RH		1	\$ 50.00
19	REAR BUMPER SENSOR		4	\$ 800.00
20	REAR BUMPER CLIP		10	\$ 80.00
21	REAR BUMPER REINFORCEMENT		1	\$ 1,800.00
22	END PANEL		1	\$ 2,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8886 f 6452 5333
COMPANY REG. NO.: 200204110W



DATE: 7/10/2020
FROM: Lee Shirley
FAX: 6452 5333
CONTACT: 8686 5188
MAKE & MODEL: MERCEDES BENZ GLE400 4MATIC
CHASSIS NO.: WDC2923562A137450
ENGINE NO.: 27682130961594
YEAR MADE: 2019
ACCIDENT DATE: 6 October 2020

Not Autho

Prumy Bgpaing

-3 day

1/10/2020

1615.45

56.00

743.32

788.50

108

ASS. REC. BY:

REF:

1.1.1

SPECIAL NETT

REAR NUMBER PLATE & HOLDER

1 \$ *R 45m* 80.00

BODY SEALANT

1 \$ *nn x* 50.00

CERAMIC COATING (*Invoice attached*)

1 *nn* \$ *2* 800.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS

\$ *30d* 1,600.00

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ *2d* 200.00

TO REMOVE & REFIT ALL SENSOR

\$ *6d* 250.00

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

\$ *nnn* 200.00 X

TO APPLY ANTI RUST COATING

\$ *nn x* 80.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ *30d* 1,200.00

TOTAL: \$ 8,260.00

7% GST: \$ 578.20

GRAND TOTAL: \$ 8,838.20