

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/200/0822/USD3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLU 2185J

at Workshop m/s

Toolsee motor

of

Insured:

SLJ2576Y

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

675k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

19/10/20 confirmed L/S @ 4500 w. Richard

(\$ 7,419.96/RED - 62%)

Veh No:

SLU 2185J

Yr Regn:

11/17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Toyota wish

c.c

1798

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

180452

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDAG20W90J00P280

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

6/10/20

D.O.I.

8/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

02/11/2020

1) TYPIST

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) __ \$ + RS __ \$

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Lump Sum I.B.I. (\$ L/S \$ 4,500.00)

TOTAL

Cti

JOO LEE MOTOR WORKSHOP

B.REG.NO.52891596K

Blk 9005 Tampines St 93 #01-252 Singapore 528839

Email : jooleemotor@yahoo.com.sg

TEL : 6784 0077 Fax : 6788 3025

Not Authorized
 done
 8/10/20
 take photo After repair
 2/5 = 4500
 4 days.

Date : 07-Oct-20

ESTIMATED REPAIR COST OF VEHICLE NO. SLU 2185 I TOYOTA WISH

List Items

1	Rear windscreen moulding	rec	\$	165.58	✓
1	Rear tailgate	body 20	\$	1,566.25	✓
1	Rear tailgate outer chrome moulding	11	\$	383.80	X
2	Rear tailgate dampers	11	\$	423.00	X
1	Rear tailgate inner trim board	11	\$	485.50	✓
2	Rear tailgate lamps	11	\$	665.80	X
1	Rear tailgate lock	20/50000	\$	350.96	✓
1	Rear tailgate logo	rec	\$	68.50	✓
1	Rear tailgate rubber	7w/11	\$	370.50	✓
1	Rear tailgate "ELEGANCE" emblem	rec	\$	85.00	✓
1	Rear tailgate "VALVE MATIC" emblem	rec	\$	72.00	✓
2	Rear taillamps	11	\$	971.00	X
2	Rear taillamp panels	11	\$	1,188.00	X
1	Rear end panel	20/5000	\$	596.50	✓
1	Rear end panel inner garnish	7w/11	\$	253.20	✓
1	Rear smart keyless sensor	one	\$	189.50	✓
1	Rear bumper	20/100 625.10	\$	991.76	✓
2	Rear bumper brackets	11	\$	177.00	X
2	Rear bumper reflectors	n/s one 68.50	\$	173.90	IPC
2	Rear bumper side retainers	MS Bent 50.50	\$	128.86	IPC
1	Rear floor board	11	\$	280.00	X
			\$	9,586.61	
			\$	2,396.65	
			\$	7,189.96	

Less 25%

P-4462.09
 25%
 P-3346.58
 S.N-340.00
 L-2000.00
 5686.58
 202
 6849

c/f: \$ 7,189.96

Special Nett Items

1	Rear windscreen sealant	nee	\$ 40	80.00
1	Rear bumper clip (1 set)	nee	\$ 50	60.00
1	Rear reverse sensor (1 set)	shall	\$ 250	350.00
1	Rear reverse camera	nn	\$ X	480.00
			\$	970.00

S/N Labour Cost

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 30	80.00
2	To remove and refit inner garnishes.	\$ 80	180.00
3	To remove and refit rear reverse sensor.	\$ 50	150.00
4	To transfer boot lid mechanism and wiring assembly.	\$ 60	120.00
5	To remove and refit rear windscreen glass.	\$ 120	180.00
6	To apply undercoating.	\$ 60	150.00
7	Panel beating.	\$ 700	1,500.00
8	To re-spray painting on the affected areas.	\$ 900	1,400.00
		\$	3,760.00

Grand Total \$ 11,919.96

Dollars: Eleven Thousand Nine Hundred Nineteen And Ninety-Six Only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: