

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SMG 8645 X**
 Model : Honda Shuttle
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 1,410.00	\$ 1,193.00 1,410.00	DDV
2	Tailgate logo	1	\$ 89.00	\$ 34.10 89.00	NEC
3	Tailgate emblem 'Shuttle'	1	\$ 78.00	\$ 48.50 78.00	NEC
4	Tailgate emblem 'HYBRID'	1	\$ 78.00	\$ 51.50 78.00	✓
5	Tailgate outer chrome garnish	1	\$ 471.00	\$ 383.10 471.00	CUTV
6	Tailgate inner lock actuator	1	\$ 221.00	\$ 187.50 221.00	SCV
7	Tailgate lock striker	1	\$ 65.00	\$ 65.00	ND
8	Tailgate weather strip	1	\$ 325.60	\$ 325.60	NDX
9	Tailgate inner trimboard	1	\$ 476.80	\$ 366.50 476.80	BRV
10	Tailgate inner handler garnish	1	\$ 168.90	\$ 168.90	ND
11	Tailgate windscreen moulding side	1	\$ 86.50	\$ 75.80 86.50	
12	Tailgate windscreen moulding Top	1	\$ 108.20	\$ 108.20	NE
13	Tailgate windscreen moulding bottom	1	\$ 108.20	\$ 108.20	
14	Tailgate lamp	2	\$ 574.00	\$ 1,148.00	BRV
15	Tailgate number plate lamp	2	\$ 48.60	\$ 97.20	NDX
16	Reverse camera	1	\$ 480.00	\$ 300.00 480.00	CUT
17	Rear bumper	1	\$ 890.00	\$ 890.00	CUT
18	Rear bumper retainer	2	\$ 44.40 91.00	\$ 88.80 182.00	NEC
19	Rear bumper bracket	2	\$ 122.00	\$ 244.00	NSX
20	Rear bumper reflector	2	\$ 148.60	\$ 297.20	NSX
21	Rear bumper reflector garnish	2	\$ 325.60	\$ 651.20	NSX
22	Rear bumper tow cap	1	\$ 86.40	\$ 86.40	ND
23	Rear bumper inner side sponge	2	\$ 58.60	\$ 117.20	ND
24	Rear antenna control module	1	\$ 248.60	\$ 248.60	ND
25	Rear fender inner trim board	2	\$ 685.30	\$ 1,370.60	ND
26	Rear end panel	1	\$ 589.65	\$ 589.65	ND
27	Rear end panel top garnish	1	\$ 177.00	\$ 177.00	ND
28	Smart buzzer	1	\$ 195.00	\$ 195.00	NS
29	Spare tyre top board	1	\$ 320.00	\$ 320.00	
30	Spare tyre panel lower splash cover	1	\$ 316.00	\$ 316.00	ND
31	Taillamp	2	\$ 435.20 781.50	\$ 870.40 1,563.00	BRV
32	Taillamp lower bracket	2	\$ 68.90	\$ 137.80	NS
33	Exhaust pipe	1	\$ 855.60	\$ 855.60	ND
34	Exhaust pipe mounting	2	\$ 89.32	\$ 178.64	X
Parts Sub Total :				\$ 13,831.29	
20% Discount				\$ 2,766.26	
PARTS TOTAL :				\$ 11,065.03	

5,853.60
 @ 20% Disc 1,170.72
 4,682.88

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ -80.00	NN
2	Tailgate sealant	1	\$ 100.00	\$ 60.00 100.00	NEC
3	Tailgate outer chrome garnish clips	1	\$ 50.00	\$ 30.00 50.00	NE
4	Tailgate inner trim board clips	1	\$ 50.00	\$ 30.00 50.00	✓
5	Tailgate windscreen primer and cleaner	1	\$ 80.00	\$ -80.00	NN
6	Tailgate windscreen sealant	1	\$ 100.00	\$ 60.00 100.00	NEC
7	Tailgate windscreen inner seal	1	\$ 60.00	\$ -60.00	NS
8	Tailgate windscreen clips	1	\$ 50.00	\$ 30.00 50.00	NEC
9	Tailgate lamp clips	2	\$ 50.00	\$ -100.00	NS
10	Tailgate lamp seal	2	\$ 60.00	\$ 60.00 120.00	NEC
11	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NEC
12	Reverse sensor c/w control module	2	\$ 250.00	\$ 200.00 500.00	SG
13	Rear number plate w/housing	1	\$ 80.00	\$ -80.00	NN
14	Rear fender inner trim board clips	2	\$ 50.00	\$ -100.00	NN
15	Rear end panel sealant	1	\$ 100.00	\$ -100.00	ND
16	Rear end panel top garnish clips	1	\$ 50.00	\$ -50.00	ND
17	Taillamp clips	2	\$ 50.00	\$ 60.00 100.00	NEC
18	Taillamp seal	2	\$ 60.00	\$ 60.00 120.00	NEC
SPECIAL NETT TOTAL :				\$ 620.00 1,890.00	

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 80.00 150.00	✓
2	R&R tailgate windscreen	\$ 120.00 250.00	✓
3	R&R reverse sensor	\$ 60.00 150.00	✓
4	R&R exhaust pipe	\$ -150.00	ND
5	Diagnostic reset fault code	\$ 120.00 300.00	NEC
6	Upholstery	\$ -300.00	NN
7	Check wiring	\$ 60.00 100.00	NE
8	Conduct water leakage test	\$ -150.00	NN
9	Panel beat	\$ 800.00 1,400.00	✓
10	Rust proofing	\$ 80.00 200.00	✓
11	Spray painting	\$ 800.00 1,400.00	✓
LABOUR TOTAL :		\$ 4,550.00	

Survey 8/10/2020
Resurvey 9/10/2020
1400 hrs
1500 hrs
TC in
TC in

PARTS TOTAL : \$ 11,065.03
SPECIAL NETT TOTAL : \$ 1,890.00
LABOUR TOTAL : \$ 4,550.00
GRAND TOTAL : \$ 17,505.03

PARTS 4,682.8
S/N 4,682.8
LABOUR 2,120.00
7,222.88
\$7,422.88

Part by part repair
Repair days 7

\$7,422.88
COR 7,222.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: