

## TRANS EUROKARS PTE LTD



## ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME :	- Mr Thoe	Teck Beng	LITD .	20072
3 ANSON ROAD			RESS: 669d Jurong West Street 64		WIP : EXCESS :	20073
#16-00 SPRINGLEAF T		#14-58				
SINGAPORE 079909		Singapore 644669		DATE:	5-Oct-20	
ATTN.:	MOTOR CLAIMS	TEL :	Mr Thoe Te			
FAX :			mi moe re	ck Beng		
VEH NO :	SJR6222Z	DATE IN :		CONTACT PERSON :	Jess 6395787	
CHASSIS NO : JM6CC1071H0111224		MILEAGE :		TYPE OF CLAIM :		
MODEL: BIANTE		DATE REG.			THIRD PARTY CLAIM	
			ATURE OF WO			
			rts Descri			
NO			QTY		REVISED	PRICES
1 REAR BUMPER	2		1	MC275-50-221FBB	de	1,170.50
2 GROMMET, RE	EAR BUMPER		2	MBP4K-50-ES1	ner!	9.40
3 PIN LOCATOR	R, REAR BUMPER		2	MGJ6B-50-1K5	ner	8.40
4 GROMMET, RE	GROMMET, REAR BUMPER 2			MB01W-51-142B	nee	6.40
5 RIVET, REAF	RIVET, REAR BUMPER 2			MA001-50-7C1	ner	7.60
6 FASTENER, F	FASTENER, REAR BUMPER 2			MGD7A-50-EA1	4.50	6.40
7 STRIPE LHS,	STRIPE LHS, REAR BUMPER			MC467-50-888	NE	86.00
8 STRIPE RHS,		1	MC467-50-878	ne	86.00	
9 STRIPE CENT	TER, REAR BUMPER		1	MC467-50-879	vis	130.10
10 REFLECTOR R	REFLECTOR RHS, REAR BUMPER			MC273-51-5L0A	Xnn	124.50
11 RETAINER RH	RETAINER RHS			MC273-50-2H1C	ZNN	48.80
12 TAPE PROTEC	12 TAPE PROTECTOR, REAR BUMPER			MG043-62-864A	nec	7.00
13 TAILGATE			1	MC2Y3-62-02XF	dar	1,699.70
14 VALVE ONEWA	Y, TAILGATE	2		MGHP9-58-867	ner	24.00
15 FINISHER, T	AILGATE	1		MC273-50-850L	art	2,018.60
16 FASTENER, T	FASTENER, TAILGATE			MEG21-51-146	14/	18.60
17 ORNAMENT, S	ORNAMENT, SKYACTIV 1			MC603-51-771A	my	117.10
18 FASTENER, R	FASTENER, REAR WINDSCREEN 1			MD204-50-896A	rec	2.80
19 SPACER, REA	SPACER, REAR WINDSCREEN 5			MGJ6A-50-897	we/	64.00
20 FASTENER, R	FASTENER, REAR WINDSCREEN 2			MC273-50-896	nei	16.40
21 TAILLAMP RH	S		1	MC273-51-150F	and	1,117.20
						-,117.20
	TOTAL PARTS					0 6,769.50
	LESS 10% No discret					676.95
	TOTAL PARTS COST					
						6,092.55
		Labo	our Descrip	tion	10 mm and 10 mm	
					V = 1 (2) - V 2 - A-V = 1 - 1 2	

_	-					
1	MZ-BR-REAR04	TO REPLACE REAR BUMPER AND TAILGATE.REPAIR ALL A	<i>€€0</i> ← ACCIDENT.	(65)	1,980.00	
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER AND TAILGATE.		1263.		
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUC		NETT	560.00	
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.			NETT	120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	٧	NX	330.00	
6	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR)		330.	660.00	
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.(WITH REVERSE CAMERA)			330.	660.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150.	250.00
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		N	N·X	250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			180	350.00
11	MZ-BR-SUNDRI		4600	20-	NETT	100.00
	Taufth 97495749		TOTAL LABOUR			7,150.00
	9	/4/10 Q 350pm 100	TOTAL PARTS		-	6,092.55
Parphin 97495749  9/20/20 8 350 pm WP  Resum before punt  Obileys			LESS EXCESS			13,242.55
			TOTAL AFTER EXCE	55		-
			GST 7%			
	1 11	hi 21/11	GRAND TOTAL			and the same of th

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR

TRANS EUROKARS PTE LTD

Authorised Signature

GRAND TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE Page 2 of 2

6596.20 4600 11,196.20 06days