



Zoom Autowerks PTE LTD

130 Bedok Reservoir Road, Eunos Spring
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

Car Number: SMU986R
Model : Hyundai Accent
Damaged Area: (Right Side Portion)
Repairer Estimation Cost of Repair :
Supplementary may be included during the cost of repair :

not Authorized
Hir
2/5 4500/
5 days

Parts / Material :

1	Rear Bumper	Re/Toon	546.32	\$	685.10	✓
2	Rear Bumper Side Retainer RH	11		\$	102.40	X
3	Rear Bumper Bracket RH	11		\$	96.40	X
4	Rear Bumper Sponge	11		\$	108.30	X
5	Rear Bumper Clips (1Set)	11	50.00	\$	60.00	✓
6	Rear Taillamp RH	11		\$	586.70	X
7	Rear Fender RH	Body PP/Seal		\$	1,405.20	✓
8	Rear Fender Inner Shield RH	Re	105.30	\$	214.20	✓
9	Rear Fender Inner Shield Clips (1Set)	11	20.00	\$	60.00	✓
10	Rear Windscreen Glass Moulding	11		\$	246.30	✓
11	Rear Door RH	Body PP		\$	896.10	✓
12	Rear Door Frame Black Sticker	11		\$	195.40	✓
13	Rear Door Inner Lock RH	2w/shot		\$	294.80	✓
14	Rear Door Outer Glass Moulding	11		\$	196.10	X
15	Rear Door Power Window Motor Linkage Assy	11	slashed	\$	425.60	✓
16	Rear Door Plastic Insulator Sheet	11		\$	68.40	X
17	Rear Door Inner Trimboard	11		\$	586.10	X
18	Rear Door Inner Trimboard Clips (1Set)	11		\$	60.00	X
19	Rear Door Weather Strip	11		\$	124.80	✓
20	Front Door RH	11			Repair	X

Parts : \$ 6,411.90
Less Parts 20% : \$ 1,282.38
Total Parts : \$ 5,129.52

Special Net Items :

Rear Windscreen Glass Sealant	11	\$	80.00	40
1 Set Wheel Caps	11	\$	485.00	150
1 pce Rear RH Tyre	11	\$	280.00	X
Total S/N Parts : \$				845.00

Labour :

To Remove, Repair & Renew Rear RH Affected Accident Areas	\$	1,200.00	800
To Putty, Spray Paint on Affected Accident Areas	\$	1,200.00	800
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Conduct Wheel Alignment	\$	150.00	60
To Remove & Install Front Right Door, Rear Right Door Trim, Garnish	\$	200.00	60
To Remove & Install Rear Fender Inner Trim, Garnish	\$	200.00	80
To Remove & Install Rear Windscreen Glass	\$	180.00	120

To Conduct Water Leakage Test
To Rust Proof Affected Areas

11 \$ 150.00 X
\$ 150.00 60
Total Labour : \$ 3,480.00

TOTAL PARTS : \$ 5,129.52
TOTAL SPECIAL NET ITEM : \$ 845.00
TOTAL LABOUR : \$ 3,480.00
TOTAL REPAIR COST : \$ 9,454.52

DATE OF SURVEY / INSPECTED:
RECOMMENDED PART BY PART / LUMP SUM :
RECOMMENDED NUMBER OF DAYS :
SURVEY BY / SURVEYOR FIRM :
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5637.05