

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Authorized
HL 8
Permy Repair
5 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 07.10.2020

Accident Date : 05.10.2020

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Stepwagen" Reg. No. SLM2062Y Claiming Against Your Insured Reg. No. SMC9380Y			
1pc	Front Bumper	3.50	<i>mycom</i> 988.50 ✓
10pcs	Front Bumper Clips		<i>ma</i> 35.00 ✓
1pc	Front Bumper Corner Retainer LH		<i>dit</i> 19.00 ✓
1pc	Front Bumper Side Fog Lamp Cover		<i>su</i> 155.00 X
1pc	Front Bumper Side Fog Lamp Cover Chrome Moulding		<i>su</i> 165.00 X
1pc	Front Wheel Rim LH <i>pr?</i>		<i>su</i> 859.20 ✓
1pc	Front Shock Absorber		479.00 ?
1pc	Front Knuckle Arm		502.00 ?
1pc	Front Knuckle Arm Bearing		150.50 ?
1pc	Front Knuckle Arm Bearing Hub		262.00 ?
	Front Lower Arm		341.00
	Less 20%		3,956.20
			791.24
			3,164.96
	Front Tyre		<i>ca</i> 190.00 <i>30%</i> SN
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		250.00 ?
	To Conduct Computerize Wheel Alignment Test		80.00 <i>60%</i>
	To Conduct High Speed Balancing		80.00 <i>20%</i>
	Labour Charge - Panel Beating, Repairing Of Front Fender, Front Door, Rocker Panel Skirt and Parts Replacement		600.00 <i>40%</i>
	To Respray Affected Areas		750.00 <i>60%</i>
		Total :	<u>5,114.96</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: