

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883  
 Email: SM\_AUTOMOTIVE@HOTMAIL.COM  
 Tel: (65) 6747 9241 Fax: (65) 6741 7276  
 RCB No.: 53231488C

07/10/2020

Blk 1 Kaki Bukit Ave 6  
 # 01-43  
 Singapore 417883

TPAXA  
 Jasper

MR053HY9305074577

Accident date: 29/09/2020

Estimated repair cost for vehicle no: SJH2897E TOYOTA VIOS E 08'  
 CHASSIS: MR053HY9305074577

S/n	Qty	Items / Nett	U/price	Amount
				\$981.45 ✓
1	1	Front R/H Door <i>Dented</i>		\$154.40 ✓
2	1	Front R/H Door Outer Handle <i>Cut</i>		\$125.60 ✓
3	1	Front R/H Door Outer Center Garnish <i>Cut</i>		\$455.40 * 298
4	1	Front R/H Door Inner Lock <i>Not Dented</i>		\$201.10 +
5	1	Front R/H Door Rubber <i>Not in</i>		\$385.80 ✓
6	1	Front R/H Door Glass Gear Motor Assy <i>Not in</i>		\$981.45 ✓
7	1	Rear R/H Door <i>Dented</i>		\$154.40 +
8	1	Rear R/H Door Outer Handle <i>Not in</i>		\$125.60 ✓
9	1	Rear R/H Door Outer Center Garnish <i>Cut</i>		\$455.40 +
10	1	Rear R/H Door Inner Lock <i>Not in</i>		\$201.10 +
11	1	Rear R/H Door Rubber <i>Not in</i>		\$385.80 ✓
12	1	Rear R/H Door Glass Gear Motor Assy <i>Dented</i>		\$981.75 +
13	1	Rear R/H Fender <i>Repair</i>		\$391.40 ✓
14	1	Rear Bumper <i>Torn</i>		\$121.25 - 3
15	1	Rear R/H Bumper Side Retainer <i>Not in</i>		\$281.45 +
16	1	Rear R/H Tail Lamp <i>Not in</i>		\$550.00 +
17	1	Rear R/H Rim <i>Not in</i>		\$1,500.00 1200
18	1	Customized Chrome Wrap <i>Not in</i>		

Subtotal :- \$8,433.35

3478.70

S.N: 1200

2609.02

**Labour charges**

To remove & refit customized chrome wrap	\$600.00 300
To remove & refit front door glass motor gear motor	\$200.00 80
To remove & refit rear door glass motor gear motor	\$200.00 80
To remove & refit cushion	\$200.00 x.
Panel beating	1860 \$1,200.00 600
Spray painting	\$1,200.00 800.
<b>Subtotal :-</b>	<b><u>\$3,000.00</u></b>
<b>Total:-</b>	<b><u>\$11,433.35</u></b>

Adrian Ly  
H/s 13/10/20.  
0 Days.  
total: 5669.02  
y/s: 4.5K  
4.5K

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

