

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5794Z****AAD2010-027***Not Authored  
1/1 Imp &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**07 OCT 2020****SHC5794Z**

VF1ABL15AUC281643

RENAULT

LATITUDE

06/10/2020

**CHINA**

16/07/2015

**PART****LIST**

|    |                                    |        |                |                 |   |
|----|------------------------------------|--------|----------------|-----------------|---|
| 1  | 1 BUMPER COVER REAR                | \$     | <i>Bu</i>      | 561.70          | ✓ |
| 2  | 1 BUMPER LOWER REAR                | \$     | <i>Na/D, 1</i> | 411.90          | ✓ |
| 3  | 1 BUMPER BRACKET CTR REAR          | \$     | <i>Sh</i>      | 98.10           | X |
| 4  | 1 BUMPER BRACKET SIDE RH REAR      | \$     | <i>Sh</i>      | 82.10           | X |
| 5  | 1 BUMPER RETAINER RH REAR          | \$     | <i>Sh</i>      | 59.80           | X |
| 7  | 1 BUMPER BRACKET SIDE LH REAR      | \$     | <i>Sh</i>      | 80.80           | X |
| 8  | 1 BUMPER RETAINER LH REAR          | \$     | <i>Sh</i>      | 54.20           | X |
| 10 | 1 BUMPER BEAM REAR                 | \$     | <i>R</i>       | 547.80          | ✓ |
| 11 | 1 BUMPER BEAM BRACKET LH REAR      | \$     | <i>R</i>       | 114.50          | X |
| 12 | 1 BUMPER BEAM BRACKET RH REAR      | \$     | <i>R</i>       | 114.50          | X |
| 13 | 1 OUTER PANEL REAR (End Panel)     | \$     | <i>R</i>       | 745.80          | X |
| 14 | 1 OUTER PANEL REAR (End Panel)TRIM | \$     | <i>Sh</i>      | 404.56          | X |
| 15 | 1 BOOT REAR                        | \$     | <i>R</i>       | 1,677.20        | X |
|    |                                    | \$     |                | <b>4,952.96</b> |   |
|    |                                    | 10% \$ |                | <b>495.30</b>   |   |
|    |                                    | \$     |                | <b>4,457.66</b> |   |

**Specical Nett**

|   |                                     |    |           |        |   |
|---|-------------------------------------|----|-----------|--------|---|
| 1 | 1SET PARKING AID                    | \$ | <i>Sh</i> | 700.00 | X |
| 2 | 1SET REAR BUMPER CLIP               | \$ | <i>Sh</i> | 66.00  | ✓ |
| 3 | 1SET BUMPER BRACKET CTR CLIP        | \$ | <i>Sh</i> | 33.00  | X |
| 4 | 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ | <i>Sh</i> | 10.00  | X |
| 5 | 1SET BUMPER RETAINER RH CLIP RR     | \$ | <i>Sh</i> | 20.00  | X |
| 6 | 1SET BUMPER BRACKET SIDE CLIP LH RR | \$ | <i>Sh</i> | 10.00  | X |
| 7 | 1SET BUMPER RETAINER CLIP LH RR     | \$ | <i>Sh</i> | 20.00  | X |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5794Z****AAD2010-027**

|                                    |           |    |                 |   |
|------------------------------------|-----------|----|-----------------|---|
| 8 1SET BUMPER LOWER REAR RIVET     | \$        | nn | 22.00           | X |
| 9 1SET BUMPER LOWER REAR CLIP      | \$        | nn | 66.00           | ✓ |
| 10 1 EXHAUST MOUNTING REAR         | \$        | nn | 17.82           | X |
| 14 1 REAR BOOT STICKER 'Trans-cab' | \$        | nn | 80.00           | X |
| 15 1 REAR BOOT STICKER '6555-3333' | \$        | nn | 80.00           | X |
| <b>TOTAL</b>                       | <b>\$</b> |    | <b>325.82</b>   |   |
| <b>TOTAL PARTS</b>                 | <b>\$</b> |    | <b>4,783.48</b> |   |

**LABOUR**

|                                                                                                                           |           |    |                 |      |
|---------------------------------------------------------------------------------------------------------------------------|-----------|----|-----------------|------|
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$        |    | 1,200.00        | 2200 |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$        |    | 2,000.00        | 2000 |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$        | nn | 170.00          | X    |
| To reinstall rear bumper parking sensor.                                                                                  | \$        |    | 170.00          | 600  |
| To transfer of bootlid fittings, attachments and perform water seepage test.                                              | \$        | nn | 170.00          | X    |
| To transfer of rear end panel fittings, attachment and perform water seepage test.                                        | \$        | nn | 170.00          | X    |
| To Check Electrical Lighting Concerned.                                                                                   | \$        |    | 170.00          | 100  |
| <b>TOTAL</b>                                                                                                              | <b>\$</b> |    | <b>4,050.00</b> |      |

**Over All Total \$ 13,291.15****(LUMP SUM)****Repair Days****10 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer