

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5794Z**AAD2010-027***Not Authored*
11/10/20

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

07 OCT 2020**SHC5794Z**

VF1ABL15AUC281643

RENAULT

LATITUDE

06/10/2020

CHINA

16/07/2015

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i>	561.70	✓
2	1 BUMPER LOWER REAR	\$	<i>Na/D, 1</i>	411.90	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sh</i>	98.10	X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sh</i>	82.10	X
5	1 BUMPER RETAINER RH REAR	\$	<i>Sh</i>	59.80	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sh</i>	80.80	X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sh</i>	54.20	X
10	1 BUMPER BEAM REAR	\$	<i>R</i>	547.80	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i>	114.50	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i>	114.50	X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i>	745.80	X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sh</i>	404.56	X
15	1 BOOT REAR	\$	<i>R</i>	1,677.20	X
		\$		4,952.96	
		10% \$		495.30	
		\$		4,457.66	

Specical Nett

1	1SET PARKING AID	\$	<i>Sh</i>	700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>R</i>	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i>	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>nn</i>	20.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5794Z**AAD2010-027**

8 1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	nn	17.82	X
14 1 REAR BOOT STICKER 'Trans-cab'	\$	nn	80.00	X
15 1 REAR BOOT STICKER '6555-3333'	\$	nn	80.00	X
TOTAL	\$		325.82	
TOTAL PARTS	\$		4,783.48	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$		1,200.00	2200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,000.00	2000
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	100
TOTAL	\$		4,050.00	

Over All Total \$ 13,291.15**(LUMP SUM)****Repair Days****10 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer