

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBE8790A

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2090795/YISHUN

Date: 08 Oct 2020

Policy No: 5108891840-01

Veh Reg No: GBE8790A

Make/Model: TOYOTA TOYOTA
HIACE VAN TURBO 5
DR MANUAL

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 06/10/2020

TP Veh Reg No: SMJ2534G

Chassis No: JTFHT02P400192244

Engine No: 1KD2598295

Reg. Date: 22/04/2016

*Not Authorized
11/10/20
Recovery After PCIA
Goley*

Estimate Repair Cost to Vehicle No :GBE8790A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	373.02	1 PC	373.02	✓
2 REAR BUMPER RH SIDE RETAINER	27.90	1 PC	27.90	✓
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
4 REAR TAILGATE	2,162.00	1 PC	2,162.00	✓
5 TAILGATE LOGO	66.78	1 PC	66.78	✓
6 TAILGATE INNER LOCK	249.62	1 PC	249.62	✓
7 TAILGATE INNER RUBBER	368.90	1 PC	368.90	?
8 RH TAILLAMP	256.90	1 PC	256.90	✓
9 RH TAILLAMP LOWER GARNISH	84.60	1 PC	84.60	✓
10 REAR END PANEL OUTER	349.80	1 PC	349.80	✓
11 REAR END PANEL INNER	1,044.20	1 PC	1,044.20	?
12 REAR RH SIDE PANEL	1,062.60	1 PC	1,062.60	✓
			6,067.32	
		Less 25%	1,516.83	4,550.49
Special Net				
13 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
14 REVERSE SENSOR	200.00	1 SET	200.00	✓
15 TAILGATE INNER PROTECTOR	280.00	1 PC	280.00	✓
			520.00	520.00
Labour				
16 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
17 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, LOCK ASSY, RH SLIDING DOOR & TRUCK ASSY, CUT, WELD & RENEW REAR END PANEL, REAR RH SIDE PANEL, KNOCK & REPAIR REAR END PANEL, REAR FLOORBOARD PANEL, REAR RH FENDER INNER PANEL & REALIGN THE SAME	1,500.00	1 LA	1,500.00	1300
18 REMOVE & REFIX REAR CARGO CANOPY	800.00	1 LA	800.00	?

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES2090795/YISHUN
Date: 08 Oct 2020
Policy No: 5108891840-01
Veh Reg No: GBE8790A
Make/Model: TOYOTA TOYOTA
HIACE VAN TURBO 5
DR MANUAL
Chassis No: JTFHT02P400192244
Engine No: 1KD2598295
Reg. Date: 22/04/2016

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 06/10/2020
TP Veh Reg No: SMJ2534G

Estimate Repair Cost to Vehicle No :GBE8790A


Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
19 PUTTY & RESPRAY ON REAR RH SIDE PANEL,REAR FLOORBOARD PANEL,REAR END PANEL,TAILGATE & ALL AFFECTED AREAS	1,000.00	1 LA	1,000.00	900.00
20 TO REWRITE ADVERTISEMENT	600.00	1 LA	600.00	?
21 RUSTPROOFING	90.00	1 LA	90.00	✓
			4,110.00	4,110.00
			Total	S\$ 9,180.49
			Add GST @ 7%	642.63
			Total Amount Payable	S\$ 9,823.12

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:


AUTHORISED SIGNATURE