



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104050

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/06/2021
Reference CC3/CTI20010840/Qea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHF 362D
Insured Veh. GBJ 3832U
Claim No. SNM20D203758
Policy No. DMCVSNA00023662001
Accident Date 07/10/2020
Inspection Date 07/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20010840/Qea3q2 Date: 10/06/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 3832U	Veh. Inspected	SHF 362D
	Policy No.	DMCVSNA00023662001	Coverage (\$)	0.00
	Claim No.	SNM20D203758	Excess (\$)	0.00
	Assign From		Assign Date	07/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS 4	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU603576608	Colour	MAROON
	Odometer	344914 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	FIRENZA	6 mm
	L/H Front Tyre	195/65 R15	FIRENZA	6 mm
	R/H Rear Tyre	195/65 R15	FIRENZA	6 mm
	L/H Rear Tyre	195/65 R15	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/10/2020	Inspection Date	07/10/2020
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 362D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER ,GUARD RR BUMPER LOWER (DISC 25%)	CRUMPLED	14.80	11.10
3	PAD ,RR BUMPER ,CTR @\$2.20 (DISC 25%)	NECESSARY	6.60	4.95
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	GUARD ,RR BUMPER ,LOWER (DISC 25%)	SCRATCHED	558.30	418.73
2	SEAL ,RR BUMPER ARM ,RH & LH	SERVICEABLE	11.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	RETAINER ,RR BUMPER ,RH	SERVICEABLE	112.70	-
1	RETAINER ,RR BUMPER ,LH	SERVICEABLE	111.50	-
1	FILLER ,RR BUMPER ,RH	SERVICEABLE	119.90	-
1	CLIPS PIECE FRT & RR BUMPER	SERVICEABLE	1.50	-
2	PAD ,RR BUMPER ,RH & LH , 1	SERVICEABLE	3.80	-
2	PAD ,RR BUMPER ,RH & LH , 2	SERVICEABLE	3.80	-
2	PAD ,RR BUMPER ,RH & LH , 3	SERVICEABLE	3.80	-
1	SEAL ,RR BUMPER ,RH	SERVICEABLE	85.20	-
1	COVER ,REAR FLOOR UNDER RH	SERVICEABLE	169.50	-
1	COVER ,REAR FLOOR UNDER CENTER	SERVICEABLE	222.60	-
1	ANTENNA ,ELECTRICAL KEY	SERVICEABLE	60.30	-
1	TAIL GATE WEATHERSTRIP BACK DOOR	SERVICEABLE	360.70	-
1	END PANEL SUBASSY ,BODY LOWER BACK	SERVICEABLE	629.80	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	COVER ,RR BUMPER ASSY	TO REPAIR SEE LABOUR	423.90	-
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
			3,874.30	793.88
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF COVER ,RR BUMPER ASSY .		876.00	200.00
	SPRAY PAINT.		1,278.00	200.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	30.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-

Report Ref No. CC3/CTI20010840/Qea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR .	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT WIRE HARNESS .	NOT NECESSARY	200.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
			2,834.00	430.00
GRAND TOTAL			6,708.30	1,223.88
RECOMMENDED COST OF REPAIRS				1,223.88

Report Ref No. CC3/CTI20010840/Qea3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 362D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 362D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

