

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                         | Adj Rpt                                          | Adj Submitted                              | Ins Auth'ed | Status                                                          |
|------|-------------|---------------|------------------------------------------------------|--------------------------------------------------|--------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 08 Oct 2020 |               | 08 Oct 2020<br>11:11<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |                                                                                                                     |                        |                                                                              |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|
| Insured:                    | -, Co. Reg. No.: -                                                                                                  |                        |                                                                              |
| Main Claimant:              | TAN YU HAO (CHEN YUHAO)                                                                                             |                        |                                                                              |
| Vehicle Reg. No.:           | SMM583L                                                                                                             | Date of Loss:          | 03/10/2020 16:00 - :59<br>[80 Months and 17 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / SNM20D203725C02                                                                                                | Policy/Cover Note No.: | DMCVSNW00066042001                                                           |
| Vehicle Reg. No. (Insured): | GBD3023U                                                                                                            | Policy No. (Claimant): |                                                                              |
|                             |                                                                                                                     | Excess:                | S\$0.00                                                                      |
| Repairer:                   | Lee Luew Sing Motor (HQ) No. 10 Ang Mo Kio Industrial Park 2A, #03-10 AMK Autopoint, 568047 Ang Mo Kio - Tel:       |                        |                                                                              |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] |                        |                                                                              |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/10/2020]   |                        |                                                                              |
| Adj Asg. Remarks:           | PLEASE SURVEY AND REVERT                                                                                            |                        |                                                                              |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## Claim Documents

**\*SMM583L (SNM20D203725C02)**  
**[GBD3023U]**

TP

**TAN YU HAO (CHEN YUHAO)**

**Oct 3 2020 4:00PM**

[-]

**Lee Luew Sing Motor**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View**
[View in Browser](#)

| Photos/Images |                 |                                   | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 1             | 09/10/20 09:12  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 2             | 09/10/20 09:12  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 3             | 09/10/20 09:12  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 4             | 09/10/20 09:12  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 5             | 09/10/20 09:12  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 6             | 09/10/20 09:12  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 7             | 09/10/20 09:12  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 8             | 09/10/20 09:12  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 9             | 09/10/20 09:12  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 10            | 09/10/20 09:12  | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 11            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 12            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 13            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 14            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 15            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 16            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 17            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 18            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 19            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 20            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 21            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 22            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 23            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 24            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 25            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 26            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 27            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 28            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 29            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 30            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 31            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 32            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 33            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 34            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 35            | 09/10/20 09:12  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                   | 3 per page                                                                                     |                                                                                       |
|---------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                                                                                 |
| 36            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 37            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 38            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 39            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 40            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 41            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 42            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 43            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 44            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 45            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 46            | 09/10/20 09:12  | General View                      |  Load JPG   |    |
| 47            | 09/10/20 09:12  | Odometer Reading                  |  Load JPG   |    |
| 48            | 09/10/20 09:12  | Chassis Number                    |  Load JPG   |    |
| 49            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG   |    |
| 50            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG   |    |
| 51            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG   |    |
| 52            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG   |    |
| 53            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG   |    |
| 54            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG   |    |
| 55            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG   |    |
| 56            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG  |   |
| 57            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 58            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 59            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 60            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 61            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 62            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 63            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 64            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 65            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 66            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 67            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 68            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 69            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 70            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 71            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 72            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 73            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 74            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 75            | 15/10/20 15:34  | Dismantled Parts                  |  Load JPG |  |
| 76            | 15/10/20 15:34  | After Repair Photo                |  Load JPG |  |
| 77            | 15/10/20 15:34  | After Repair Photo                |  Load JPG |  |
| 78            | 15/10/20 15:34  | After Repair Photo                |  Load JPG |  |
| 79            | 15/10/20 15:34  | After Repair Photo                |  Load JPG |  |
| 80            | 15/10/20 15:34  | After Repair Photo                |  Load JPG |  |
| 81            | 15/10/20 15:34  | After Repair Photo                |  Load JPG |  |
| 82            | 15/10/20 15:34  | After Repair Photo                |  Load JPG |  |
| 83            | 15/10/20 15:34  | After Repair Photo                |  Load JPG |  |

| Photos/Images |                 |                                   | 3 per page ▾ | <input checked="" type="checkbox"/>          |
|---------------|-----------------|-----------------------------------|--------------|----------------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |              | Thumbnail Print                              |
| 84            | 15/10/20 15:34  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 85            | 15/10/20 15:34  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 86            | 15/10/20 15:34  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 87            | 15/10/20 15:34  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 88            | 15/10/20 15:34  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 89            | 15/10/20 15:34  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 90            | 15/10/20 15:34  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 91            | 15/10/20 15:35  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 92            | 15/10/20 15:35  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 93            | 15/10/20 15:35  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 94            | 15/10/20 15:35  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 95            | 15/10/20 15:35  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |
| 96            | 15/10/20 15:35  | After Repair Photo                |              | Load JPG <input checked="" type="checkbox"/> |

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/CTI20010843/GSF3S2**Date:** 28/10/2020REFERENCE

|                              |                                               |                             |                    |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMCVSNW00066042001 |
| <b>Claimant Vehicle No :</b> | SMM583L                                       | <b>Insured Vehicle No :</b> | GBD3023U           |
| Date of Loss:                | 03/10/2020                                    | Nature of Claim:            | TP                 |
|                              |                                               | Claim No:                   | SNM20D203725C02    |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMM583L</b>                    | Engine No:  | 27491030132736    |
| Make & Model:               | MERCEDES-BENZ C180K, 1.6 (A)      | Chassis No: | WDD2040312A928877 |
| Reg. Date:                  | 16/01/2014 (Man. Year: 2013)      | Odometer:   | 148314 km         |
| Colour:                     | Blue                              |             |                   |
| Engine Capacity:            | 1595 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 225/45 R17       | Rear Tyre Size:  | 225/45 R17       |
| Front Left Side:  | Continental 8 mm | Rear Left Side:  | Continental 8 mm |
| Front Right Side: | Continental 8 mm | Rear Right Side: | Continental 8 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                    | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items      | 0.00              | 0.00              | 0.00              |               |
| Labour                   | 0.00              | 0.00              | 0.00              |               |
| Paintwork Labour         | 0.00              | 0.00              | 0.00              |               |
| Towing                   | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b> | <b>0.00</b>       | <b>0.00</b>       | <b>0.00</b>       |               |

INSPECTION

|                             |                          |                                                                                                               |
|-----------------------------|--------------------------|---------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 08/10/2020               |                                                                                                               |
| Date Inspected:             | 08/10/2020 Inspected At: | Lee Luew Sing Motor (HQ)<br>No. 10 Ang Mo Kio Industrial Park 2A, #03-10 AMK<br>Autopoint<br>Singapore 568047 |
| Estimated Period of Repair: | 5.0 days                 |                                                                                                               |

**Adjuster:** XING GUO QIANG**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

10/28/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                               |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 28 Oct 2020)                 |
| <b>Parts:</b>        | 143                                                                                                                                                                          | MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                             |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMM583L)                                                                                                                                     |                                                               |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                               |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                               |

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >