

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 81836567

TP Budget Direct.
 Xiao Chan.

ESTIMATE

Repair Code : CLM16481

Date in : 06/10/2020

Vehicle Num. : SLK672K

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104557481/1ZRY330811

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>to be</i>	1	581.90	✓ 581.90
REAR BUMPER SIDE RETAINER L/R <i>RH New</i>	2	65.00	65 130.00
REAR RH DOOR <i>Dented</i>	1	1248.50	✓ 1,248.50
REAR RH DOOR BLACK TAPE <i>new</i>	1	63.00	✓ 63.00
REAR RH DOOR INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	25.00	x 50.00
REAR RH DOOR MECHANISM LOCK <i>new</i>	1	563.00	x 563.00
REAR RH DOOR OUTER CHROME MOULDING <i>new</i>	1	93.00	x 93.00
REAR RH DOOR OUTER FRAME GARNISH (VERTICAL) <i>new</i>	1	93.00	x 93.00
REAR RH DOOR WEATHER STRIP <i>new</i>	1	195.00	x 195.00
REAR RH DOOR WINDOW GLASS CHANNEL <i>Not New</i>	1	97.00	x 97.00
REAR RH FENDER <i>Dented</i>	1	1149.00	✓ 1,149.00
REAR RH FENDER INNER SHIELD COVER <i>new</i>	1	86.00	x 86.00
REAR RH SPORT RIM <i>at</i>	1	2010.70	980 (SN) 2,010.70
REAR RH WHEEL BEARING <i>Dented</i>	1	654.10	520 654.10
REAR WINDSCREEN MOULDING <i>new</i>	1	198.70	✓ 198.70

3826:10
 2869:57
 S-N 980

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 81836567

ESTIMATE

Repair Code : CLM16481

Date in : 06/10/2020

Vehicle Num. : SLK672K

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104557481/1ZRY330811

		Subtotal before discount	7,212.90
	Percentage discount 25%		1,803.23
		Sub-total 1	5,409.68
REAR BUMPER CLIPS - SET	<i>new</i>	1	50.00 30 50.00
REAR RH DOOR TRIM BOARD CLIPS - SET	<i>new</i>	1	50.00 30 50.00
REAR WINDSCREEN SEALANT	<i>Not new</i>	1	60.00 4 60.00
		Subtotal before discount	160.00
	Percentage discount 0%		0.00
		Sub-total 2	160.00
		Parts-total	5,569.68

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor. ✓ 60.00
- To remove and refit rear windscreen(to FR) ~~120 150.00~~
- To remove, reinstall rear suspension and undercarriage part. (to FR) 80 150.00
- To road test driving, check and resetting wheel alignments system. 80 100.00
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR) 60 140.00
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle. 80 100.00
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. 800 1,000.00
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. 800 1,300.00
- To apply anti-rust chemical on repaired and replaced panel. 80 100.00

Labour Total **3,100.00**

Parts & Labour Total **8,669.68**

total 6009.57
4.8k
0.6 days
4.8k . 0.6 days