ASS. REČ. BY: 490066 REF: CC6/11	, 200108×1/Ug,3		
	SIGNMENT		
From: Date:	Veh No: SMHSS2C Yr Regn: 09/1/19		
Estimated Cost:	Type: McCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /		
OD / (P) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or		
To Inspect Vehicle No: SMH SX 2C	Make: Manda FIT c.c /3/7		
at Workshop m/s Choo Motur	Colour Sihe A/C: Insured / Std / NI / NA		
of	Sp.Reading 243&9 T/Radio: Insured / Std / NI / NA		
Insured: GBK 1682T	Eng/No:		
Policy No.	C/No: GK3133789/		
Claims No.	Gen. Cond: Good / Pair / Poor / Burnt		
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or		
(Client's Record)	Brake: Inorder Lammed / Leaked / Burnt or		
Make of Veh:	Modi: (Nil S/Rim / STD A/Rim or		
	Tyre Size: F: 175/70114		
(Policy Condition)	R:		
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /		
repair at the time of inspection.	Τογο / γοκό 🖟		
Bal. or Market Value: 604.	Front Rear		
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm R/Bal. mm		
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 7, mm L/Bal. 7 mm		
Est. Repairs: / days Res.: Yes or No	D.O.A. 8/10/20 D.O.I. 8/10/20		
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at		
CA / REV / REP. / 24 HRS 280	Des. of Damages : Frt / Rear / O/S / N/S / U/C Rooftop or		
Vehicle: IN / OUT	gen &		
Date: Person Contacted: how high	The U/C / Chassis frame / Body Structure affected due to collision.		
Date / Time Action / Instruction Out Art A 26140 R-1 Rys 3~	1		
17426140 B-1 kys 5m			
Nott 33860			
0/10/20 M/3 8/4,200 confined with Alm			
1/10/20 M/S . 45 LOD CONTINUE WILL HUM			
Date/Time, File Pass to? : Preli. Report	David Of David		
rem. Keport	Days Of Repair:		
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:		
Add Fee	Transportation: Site Insp (\$) _ S + RS _ SI		
Additee	7		
Report Format :			
ump Sum / I R I: /¢			
)	: Weekend (\$		
	TOTAL		

CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVE 6 #01-39 AUTOBAY SINGAPORE 417883 Not Authorist
Like

d/c 414200(

1 Sdays.

8/10/10

VEHICLE No:SMH 552C

1PC	REAR WINDSRCEEN Shothered 1150.20	
1PC	and the state of t	\$1,422.30
1PC	REAR WINDSCREEN MOULDING ALL TAILGATE ROLL 99	\$68.10 /
1PC		\$845.20
1PC		\$355.40
1PC	TAILGATE OUTER OPENER SWITCH Dange - 220.20	\$255.20
71. T	TAILGATE 'H' LOGO	\$35.00
1PC	TAILGATE 'FIT' EMBLEM	\$38.00
1PC	TAILGATE REAR WIPER ARM	\$188.60
1PC	TAILGATE REAR WIPER BLADE	\$65.50
1PC	TAILGATE REAR WIPER MOTOR Suffici	\$485.20
2PCS	TAILGATE LICENCE PLATE LAMPS @\$85.00 11	\$170.00 🗶
2PCS	TAILGATE REFLECTORS @\$281.00 cng /66-20 x2 = 3 32.40	\$562.00
1PC	TAILGATE INNER LOCK Tw./Jm /45.20	\$209.20
1PC	TAILGATE INNER TRIM BOARD DIS /cra 322.50	\$388.20
1SET	TAILGATE INNER TRIM BOARD CLIPS	\$30.00
1PC	TAILGATE INNER PULL GARNISH 11	\$35.00 🗶
1PC	TAILGATE WEATHERSTRIP 1w1	\$166.80
1PC		\$1,280.00
1PC	REAR BUMPER DIS 492-70	\$645.50
1PC	REAR BUMPER LOWER CENTRE BLACK GARNISH つび	\$115.00
2PCS	REAR BUMPER LOWER SIDE BLACK GARNISHS @\$65.00 CVC	\$130.00
2PCS	REAR BUMPER SIDE RETAINERS @\$22.50 As ca	\$45.00 IPC
1PC	REAR BUMPER SPLASH SHIELD N/S 7000	\$88.20
1SET	REAR BUMPER CLIPS	\$30.00
1PC	REAR BUZZLE SENSOR (***)	\$350.00
1PC	REAR ANTENNA SENSOR CAL 215-40	\$320.00
2PCS	TAILLAMPS @\$450.20 NS BNO OLS GNO 380.50x2:761.00	\$900.40
2PCS	TAILLAMP HOUSING PANELS @\$425.00 Sody in 315.xv=630.00	\$850.00
1PC	REAR END PANEL Body DD 328.00	\$366.00
1PC	REAR END PANEL TOP GARNISH DIS,	\$198.00
1PC	REAR FLOOR PANEL Crumpled / Buc	\$945.20
1PC	REAR FLOOR PANEL TOP BOARD WOOD	\$365.00
1PC	REAR FLOOR TOOLS SPONGE だい タリチ・2つ	\$680.00
1PC	REAR FENDER INNER TOP GARNISH N/S CNE	\$145.20
1PC	REAR FENDER INNER WHEEL HOUSING PANEL N/S 3.350 PYG-20	\$988.20
2PCS	REAR FENDERS @\$971.00 NIS DIS R	\$1,942.00 17
2PCS	REAR FENDER INNER TRIMS @\$365.00 MS De	\$730.00 12
1SET	REAR FENDER INNER TRIM CLIPS 11	\$30.00 💉
2PCS	REAR FENDER GLASS @\$299.00 ^ 1	\$598.00 🗴
2PCS	REAR DOORS @\$785.20	\$1,570.40 🗶
2PCS	REAR DOOR INNER LOCKS @\$266.50 AS Done	\$533.00 126
2PCS	REAR DOOR INNER BOARDS @\$288.00 \mathcal{A}	\$576.00 🗶
1PC	REAR EXHAUST (207	\$645.00
1.0	1206	7045.00

1PC 1PC 1PC 2PCS 2PCS 1PC 2PCS 2PCS	REAR EXHAUST HEAT SHIELD REAR EXHAUST MOUNTING CENTRE EXHAUST PIPE REAR SHOCK ABSORBERS @\$215.00 REAR WHEEL HUB BEARINGS @\$292.00 REAR AXLE BEAM Suffful REAR AIR VENTS @\$35.00 A 1 REAR FLOOR INNER SIDE PANELS @\$188.00	\$185.00 \(\) \$35.00 \(\) \$942.30 \(\) \$430.00 \(\) \$584.00 \(\) \(\) \$570.00 \(\) \$376.00 \(\) \$24,128.10
1PC 1PC 1PC 1PC 1SET 1SET 1PC 1PC 1SET 1SET	REAR WINDSCREEN SOLAR FILM REAR WINDSCREEN SEALANT REAR WINDSCREEN INNER SEAL REAR LICENCE PLATE W/HOLDER REAR REVERSE CAMERA REAR BUMPER REVERSE SENSOR REAR FENDER GLASS SEALANT REAR END PANEL SEALANT REAR FLOOR PANEL INSULATOR REAR SEAT FRAME BRACKET NO REAR SEAT FRAME BRACKET NO REAR WINDSCREEN SOLAR FILM ALL REAR REVERSE CAMERA Should REAR FENDER GLASS SEALANT REAR FLOOR PANEL INSULATOR REAR SEAT FRAME BRACKET NO	\$280.00 200 \$50.00 40 \$30.00 550.00 40 \$380.00 350 \$250.00 200 \$80.00 30 \$50.00 550.00 550.00
	TO CHECK WIRING TO DISMANTLE & REPLACED REVERSE SENSOR TO DISMANTLE & REFIX REAR WINDSCREEN TO DISMANTLE & REFIX CUSHION UPHOLSTERY TO DISMANTLE & REPLACED REAR EXHAUST TO DISMANTLE & REFIX FUEL TANK TO DISMANTLE & REFIX FUEL TANK TO DISMANTLE & REFIX REAR UNDER CARRIAGE TO CONDUCT WHEEL ALIGNMENT TO DISMANTLE & REFIX REAR FENDER GLASS LH/RH TO MOUNT VEHICLE ON CAR O-LINER TO TRANSFER TAILGATE MECHANISM TO SPRAY RUST PROOFING	\$80.00 30 \$80.00 50 \$150.00 120 \$150.00 60 \$150.00 60 \$380.00 250 \$120.00 60 \$150.00 60 \$150.00 60 \$150.00 60 \$200.00 120

LKK Auto Consultants hence notify the Repairer of the following:

TOTAL

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third pady survey a rena "Without Prejudice" basis
- Supplementary item's) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

LABOUR FOR PANEL BEATING & REPLACED PARTS

TO PUTTY & SPRAY PAINTING

14887.7 1. 1.910.16 1. 1.910.16 1. 1.910.16 1. 1.910.16

\$3,800.00 2400

\$2,500.00 1500

\$34,918.10