



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102560

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 14/04/2021  
Reference CC4/FCI20010856/T1es3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. SMT 1284G  
Insured Veh. SH 7660G  
Claim No. D20004000MFSH  
Policy No. D-20094922MFSH  
Accident Date 30/09/2020  
Inspection Date 09/10/2020

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 500.00        |
| <b>Subtotal</b>                | <b>500.00</b> |
| <b>GST (7%)</b>                | <b>35.00</b>  |
| <b>Grand Total</b>             | <b>535.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                       |                                                                                                                                        |                                                                   |                              |            |
|-----------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|------------------------------|------------|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877 |                                                                                                                                        |                                                                   | Ref: CC4/FCI20010856/T1es3q2 |            |
|                                                                                         |                                                                                                                                        |                                                                   | Date: 14/04/2021             |            |
|                                                                                         |                                                                                                                                        |                                                                   | Code: FCI2                   |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                       |                                                                                                                                        |                                                                   |                              |            |
|                                                                                         | Insured Veh.                                                                                                                           | SH 7660G                                                          | Veh. Inspected               | SMT 1284G  |
|                                                                                         | Policy No.                                                                                                                             | D-20094922MFSH                                                    | Coverage (\$)                | 0.00       |
|                                                                                         | Claim No.                                                                                                                              | D20004000MFSH                                                     | Excess (\$)                  | 0.00       |
|                                                                                         | Assign From                                                                                                                            | VIC                                                               | Assign Date                  | 08/10/2020 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                           |                                                                                                                                        |                                                                   |                              |            |
|                                                                                         | Make & Model                                                                                                                           | MAZDA 2                                                           | c.c                          | 1496       |
|                                                                                         | Engine No.                                                                                                                             | HIDDEN                                                            | Year of Reg.                 | 2020       |
|                                                                                         | Chassis No.                                                                                                                            | JM6DJ2HAA01300395                                                 | Colour                       | WHITE      |
|                                                                                         | Odometer                                                                                                                               | 7522 KM                                                           | Steering                     | IN ORDER   |
|                                                                                         | Brakes                                                                                                                                 | IN ORDER                                                          | Modification                 | SPORTS RIM |
|                                                                                         | General                                                                                                                                | GOOD                                                              |                              |            |
| <b>3. Conditions of Tyres</b>                                                           |                                                                                                                                        |                                                                   |                              |            |
|                                                                                         |                                                                                                                                        | Size                                                              | Make                         | Balance    |
|                                                                                         | R/H Front Tyre                                                                                                                         | 185/60 R16                                                        | TOYO                         | 6 mm       |
|                                                                                         | L/H Front Tyre                                                                                                                         | 185/60 R16                                                        | TOYO                         | 6 mm       |
|                                                                                         | R/H Rear Tyre                                                                                                                          | 185/60 R16                                                        | TOYO                         | 6 mm       |
|                                                                                         | L/H Rear Tyre                                                                                                                          | 185/60 R16                                                        | TOYO                         | 6 mm       |
| <b>4. Description of Damages</b>                                                        |                                                                                                                                        |                                                                   |                              |            |
|                                                                                         | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br><br>DAMAGES SEE DETAILS.                                                         |                                                                   |                              |            |
| <b>5. General Information</b>                                                           |                                                                                                                                        |                                                                   |                              |            |
|                                                                                         | Accident Date                                                                                                                          | 30/09/2020                                                        | Inspection Date              | 09/10/2020 |
|                                                                                         | Survey held at                                                                                                                         | TRANS EUROKARS PTE LTD<br>12 SUNGEI KADUT AVE<br>SINGAPORE 729648 |                              |            |
| <b>5a. Remarks</b>                                                                      |                                                                                                                                        |                                                                   |                              |            |
|                                                                                         | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                   |                              |            |
| <b>5b. Estimate Days of Repair</b>                                                      |                                                                                                                                        |                                                                   |                              |            |
|                                                                                         | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                   | 3 Working Days               |            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 1284G

| Qty                                | Description of Parts          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                               |               |                           |                   |
| 1                                  | REAR BUMPER                   | DEFORMED      | 893.40                    | 893.40            |
| 1                                  | BRACKET,CENTER                | NOT NECESSARY | 5.40                      | -                 |
| 2                                  | STAY ,REAR BUMPER             | NOT NECESSARY | 22.80                     | -                 |
| 1                                  | RETAINER RHS                  | NOT NECESSARY | 27.20                     | -                 |
| 4                                  | GROMMET ,REAR BUMPER          | NECESSARY     | 10.80                     | 10.80             |
| 7                                  | FASTENER ,REAR BUMPER         | NECESSARY     | 21.00                     | 21.00             |
| 4                                  | CLIP,REAR BUMPER              | NECESSARY     | 14.80                     | 14.80             |
| 5                                  | TAPE PROTECTOR ,REAR BUMPER   | NECESSARY     | 23.50                     | 23.50             |
| 1                                  | RETAINER CENTER RHS ,SENSOR   | NECESSARY     | 18.20                     | 18.20             |
| 1                                  | SENSOR CENTER RHS ,ULTRASONIC | NOT WORKING   | 180.90                    | 180.90            |
| 1                                  | REAR END PANEL                | NOT NECESSARY | 477.10                    | -                 |
| 1                                  | GASKET LHS ,TAILGATE          | NECESSARY     | 54.30                     | 54.30             |
| 1                                  | GASKET RHS ,TAILGATE          | NECESSARY     | 54.30                     | 54.30             |
| 1                                  | MASCOT ,REAR                  | NOT NECESSARY | 61.20                     | -                 |
| 1                                  | ORNAMENT ,MAZDA 2             | NOT NECESSARY | 58.30                     | -                 |
| 1                                  | ORNAMENT ,SKYACTIV            | NOT NECESSARY | 68.00                     | -                 |
| 1                                  | CAMERA-BACK MONITOR           | NOT NECESSARY | 846.00                    | -                 |
| 1                                  | ANTENNA                       | NOT NECESSARY | 111.10                    | -                 |
| 1                                  | CLIP ,ANTENNA                 | NOT NECESSARY | 2.70                      | -                 |
| 2                                  | LAMP ,LICENSE                 | NOT NECESSARY | 111.60                    | -                 |
| 1                                  | UNDER COVER ,REAR BUMPER      | NOT NECESSARY | 70.40                     | -                 |
| 4                                  | FASTENER ,UNDER COVER         | NOT NECESSARY | 12.00                     | -                 |
| 1                                  | SILENCER                      | NOT NECESSARY | 1,105.90                  | -                 |
| 1                                  | GASKET ,SILENCER              | NOT NECESSARY | 15.40                     | -                 |
|                                    |                               |               | 4,266.30                  | 1,271.20          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                               |               |                           |                   |
| 1                                  | SUNDRIES (SN)                 | NECESSARY     | 100.00                    | 20.00             |
| 1                                  | NUMBER PLATE (SN)             | CRACKED       | 70.00                     | 70.00             |
|                                    |                               |               | 170.00                    | 90.00             |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                | Description of Parts                                                                                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                    | <b>LABOUR</b>                                                                                        |               |                           |                   |
|                                    | TO LABOUR REAR BUMPER AND REAR END PANEL.                                                            |               | 2,970.00                  | 660.00            |
|                                    | TO RESPRAY REAR BUMPER ,REAR END PANEL AND TAILGATE.                                                 |               | 2,520.00                  | 630.00            |
|                                    | TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.                                                     | NOT NECESSARY | 180.00                    | -                 |
|                                    | TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION . | NOT NECESSARY | 660.00                    | -                 |
|                                    | TO TRANSFER REVERSE SENSOR .                                                                         |               | 330.00                    | 330.00            |
|                                    | TO TRANSFER REVERSE CAMERA.                                                                          |               | 330.00                    | 330.00            |
|                                    | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                                                   |               | 250.00                    | 150.00            |
|                                    | TO CARRY -OUT BODY CAVITY PRESERVATION .                                                             | NOT NECESSARY | 250.00                    | -                 |
|                                    | TO REMOVE & INSTALL REAR EXHAUST ASSY .                                                              | NOT NECESSARY | 990.00                    | -                 |
|                                    | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                                                      |               | 350.00                    | 180.00            |
|                                    |                                                                                                      |               | 8,830.00                  | 2,280.00          |
| <b>GRAND TOTAL</b>                 |                                                                                                      |               | <b>13,266.30</b>          | <b>3,641.20</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                                                      |               |                           | <b>3,641.20</b>   |

Report Ref No. CC4/FCI20010856/T1es3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMT 1284G

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

