



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE PTE LTD 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Lam Khee Chong ADDRESS : 14 West Coast Grove Singapore 127825 TEL : 96960225		WIP : 20031 EXCESS : DATE: 2-Oct-20	
VEH NO :	SMT1284G	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6DJ2HAA01300395	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 2	DATE REG. :	27-Mar-20	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1	MDH4T-50-221 BB	de ✓	893.40 ✓
2	BRACKET, CENTER	1	MKD53-50-251	nn X	5.40
3	STAY, REAR BUMPER	2	MD09W-50-271A	nn X	22.80
4	RETAINER RHS	1	MD09H-50-2H1A	nn X	27.20
5	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	nei ✓	10.80 ✓
6	FASTENER, REAR BUMPER	7	MB45A-56-146A	nei ✓	21.00 ✓
7	CLIP, REAR BUMPER	4	MC274-50-133	nei ✓	14.80 ✓
8	TAPE PROTECTOR, REAR BUMPER	5	MBCKA-50-EM1	nei ✓	23.50 ✓
9	RETAINER CENTER RHS, SENSOR	1	MKD47-67-UC5A64	nei ✓	18.20 ✓
10	SENSOR CENTER RHS, ULTRASONIC	1	MGMK6-67-UC1 64	nn ✓	180.90 ✓
11	REAR END PANEL	1	MDJYS-70-75Z	nn X	477.10
12	GASKET LHS, TAILGATE	1	MDA6A-51-3J8	nei ✓	54.30 ✓
13	GASKET RHS, TAILGATE	1	MDA6A-51-3H8	nei ✓	54.30 ✓
14	MASCOT, REAR	1	MD09W-51-730	nn X	61.20
15	ORNAMENT, MAZDA 2	1	MDB2M-51-721	nn X	58.30
16	ORNAMENT, SKYACTIV	1	MD09W-51-771	nn X	68.00
17	CAMERA-BACK MONITOR	1	MD09H-67-RC0	nn X	846.00
18	ANTENNA	1	MKD47-67-6NXA	nn X	111.10
19	CLIP, ANTENNA	1	MKD45-67-6NYA	nn X	2.70
20	LAMP, LICENSE	2	MD09H-51-270B	nn X	111.60
21	UNDER COVER, REAR BUMPER	1	MD09T-56-351A	nn X	70.40
22	FASTENER, UNDER COVER	4	MB45A-56-146A	nn X	12.00
23	SILENCER	1	MP521-40-100B	nn X	1,105.90
24	GASKET, SILENCER	1	MP549-40-305	nn X	15.40
TOTAL PARTS					4,266.30
TOTAL PARTS COST					4,266.30
Labour Description					

1	MZ-SP-SREAR1	^{labor} TO RESPRAY REAR BUMPER AND REAR END PANEL.	660	2,970.00	✓
2	MZ-SP-SREAR4	✓ TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE.	630	2,520.00	✓
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	NETT X	180.00	
4	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	X	660.00	
5	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS.	3 ✓	330.00	✓
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	✓	330.00	✓
7	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	cm — NETT	70.00	✓
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.	250.00	✓
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	250.00	
10	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.	X	990.00	
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	350.00	✓
12	MZ-BR-SUNDRI	SUNDRIES.	20. NETT	100.00	✓

Taughlin 97475749
 WP 9/10/20 @ 320
 • 3 days
 Resurvey before paint
 Taughlin @ 1/10/20 W.H.

TOTAL LABOUR	-	9,000.00
TOTAL PARTS	-	4,266.30
TOTAL	-	13,266.30
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE Page 2 of 2