



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301582

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 16/03/2023
Reference CC6/CTI20010860/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMH 3603U
Insured Veh. GBK 2826P
Claim No. SNM20D203728
Policy No. DMCVSNA00057092000
Accident Date 02/10/2020
Inspection Date 08/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20010860/Upa3q2 Date: 16/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 2826P	Veh. Inspected	SMH 3603U	
Policy No.	DMCVSNA00057092000	Coverage (\$)	0.00	
Claim No.	SNM20D203728	Excess (\$)	0.00	
Assign From		Assign Date	08/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ACR500080383	Colour	WHITE	
Odometer	150109 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	HABILEAD	6 mm	
L/H Front Tyre	215/60 R16	HABILEAD	6 mm	
R/H Rear Tyre	215/60 R16	HABILEAD	6 mm	
L/H Rear Tyre	215/60 R16	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2020	Inspection Date	08/10/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 3603U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	1,250.10	681.10
1	REAR BUMPER REFLECTOR O/S	NOT NECESSARY	98.80	-
1	REAR BUMPER SIDE HOLDER O/S	SERVICEABLE	65.50	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR FENDER O/S	BADLY DENTED	1,685.10	1,085.10
1	REAR FENDER INNER TRIM BOARD O/S	SERVICEABLE	845.10	-
1	SET REAR FENDER INNER TRIM BOARD CLIPS O/S	NOT NECESSARY	50.00	-
1	REAR FENDER UNDER SPLASH SHIELD O/S	NOT NECESSARY	109.50	-
1	REAR FENDER GLASS O/S	NOT NECESSARY	680.00	-
1	REAR AIR CON BLOWER	CRACKED	2,480.10	2,111.10
1	TAILLAMP O/S	NOT NECESSARY	655.10	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	622.30	-
1	REAR SHOCK ABSORBER O/S	NOT NECESSARY	299.20	-
1	REAR WHEEL HUB BEARING O/S	NOT NECESSARY	450.50	-
	LESS 25% DISCOUNT		-	-981.83
			9,341.30	2,945.47
<u>SPECIAL NETT ITEMS</u>				
1	REAR SPORT RIM O/S (SN)	TO REPAIR SEE LABOUR	680.00	-
1	REAR FENDER GLASS SEALANT O/S (SN)	NECESSARY	50.00	40.00
			730.00	40.00
<u>LABOUR</u>				
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REFIX REAR BUMPER REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR FENDER GLASS O/S .		150.00	100.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		120.00	80.00
	TO REFILL AIR CON GAS.		150.00	50.00
	TO CONDUCT WHEEL ALIGNMENT .		100.00	60.00
	TO DISMANTLE & REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	180.00	-

Report Ref No. CC6/CTI20010860/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY RUST PROOFING .		80.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR SPORT RIM O/S.		1,080.00	800.00
	TO PUTTY & SPRAY PAINTING .		1,500.00	600.00
			3,490.00	1,790.00
GRAND TOTAL			13,561.30	4,775.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CC6/CTI20010860/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 3603U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 3603U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 3603U

RE-INSPECTION

