

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG: 200707743D GST REG: 200707743D

*Vincent*

6-Oct-19

## ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8971 P

		\$	1,789.90
1 pc	Rear o/s door <i>X R</i>	\$	110.00
1 pc	Rear o/s door protector <i>X</i>	\$	346.40
1 pc	Wheel cover <i>/ CUT</i>	\$	459.40
1 pc	Rear bumper <i>X R</i>	\$	33.10
1 pc	Rear bumper o/s side bracket <i>X</i>	\$	1,091.50
1 pc	Rear o/s rim <i>X</i>	\$	290.00
1 pc	o/s rocker panel garnish <i>X</i>	\$	65.50
1 pc	Rear o/s fender inner shield (front piece) <i>X</i>	\$	73.60
1 pc	Rear o/s fender inner shield (rear piece) <i>X</i>	\$	393.10
1 pc	Rear o/s lower arm <i>X</i>	\$	92.80
1 pc	Rear o/s assist arm <i>X</i>	\$	121.00
1 pc	Rear o/s trailing arm <i>X</i>	\$	230.50
1 pc	Rear o/s shock absorber <i>X</i>	\$	454.00
1 pc	Rear o/s knuckle bearing <i>X</i>	\$	386.90
1 pc	Rear o/s knuckle arm <i>X</i>	\$	5,937.70
		\$	1,187.54
	Less 20%	\$	4,750.16

### S/NETT

1 set	Rear bumper clips <i>/ NR</i>	\$	48.00
1 set	o/s door stickers <i>/ NR</i>	\$	100.00
1 pc	Rear o/s fender sticker <i>/ NR</i>	\$	60.00
1 pc	Rear o/s tyre <i>X</i>	\$	200.00
1 set	Rear o/s fender inner shield clips <i>X</i>	\$	28.00
1 set	Sealant <i>X</i>	\$	50.00

6-Oct-19

**ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8971 P**

To dismantle and replace the rear o/s undercarriage	\$ 250.00 X
To check rear o/s wheel alignment	\$ 80.00 60
To dismantle and refit the inner component of the Rear o/s door into new shell door	\$ 150.00 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender etc	\$ 1,000.00 400
To putty and spray painting on rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper, rear o/s fender inner	\$ 1,000.00 600
To apply rusproof on repaired panels	\$ 150.00 X
	<u>\$ 8,166.16</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Steve (LKK) WTL PAL  
8/10/20, 3-00pm  
3 days  
P/P (if no part)  
By AL MY