

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 *Vincent*

CO. REG: 200707743D GST REG: 200707743D

6-Oct-19

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8971 P

1 pc	Rear o/s door	X R	\$	1,789.90
1 pc	Rear o/s door protector	X MM	\$	110.00
1 pc	Wheel cover	/ MM	\$	346.40 ✓
1 pc	Rear bumper	X R	\$	459.40
1 pc	Rear bumper o/s side bracket	X MM	\$	33.10
1 pc	Rear o/s rim	X MM	\$	1,091.50
1 pc	o/s rocker panel garnish	X MM	\$	290.00
1 pc	Rear o/s fender inner shield (front piece)	X MM	\$	65.50
1 pc	Rear o/s fender inner shield (rear piece)	X MM	\$	73.60
1 pc	Rear o/s lower arm	X MM	\$	393.10
1 pc	Rear o/s assist arm	X MM	\$	92.80
1 pc	Rear o/s trailing arm	X MM	\$	121.00
1 pc	Rear o/s shock absorber	X MM	\$	230.50
1 pc	Rear o/s knuckle bearing	X MM	\$	454.00
1 pc	Rear o/s knuckle arm	X MM	\$	386.90
			\$	<u>5,937.70</u>
			\$	Less 20%
			\$	<u>4,750.16</u>

346.40
- 20%
277.12

S/NETT

1 set	Rear bumper clips	X X MM	\$	48.00 X
1 set	o/s door stickers	/ MC	\$	100.00 80 ✓
1 pc	Rear o/s fender sticker	/ MC	\$	60.00 40 ✓
1 pc	Rear o/s tyre	X MM	\$	200.00 X
1 set	Rear o/s fender inner shield clips	X MM	\$	28.00 X
1 set	Sealant	X MM	\$	50.00 X

120

6-Oct-19

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8971 P

To dismantle and replace the rear o/s undercarriage	\$ 250.00	X
To check rear o/s wheel alignment	\$ 80.00	60
To dismantle and refit the inner component of the Rear o/s door into new shell door	\$ 150.00	X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00	X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender etc	\$ 1,000.00	400
To putty and spray painting on rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper, rear o/s fender inner	\$ 1,000.00	600
To apply rusproof on repaired panels	\$ 150.00	X
	<u>\$ 8,166.16</u>	

1060

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

P-277-12

N1-120

L-1060

1457-12

Steve (LKK)

WAL P&L

8/10/20, 3:00pm

3 days

P/P (if no part)

Ry AL MY