

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

CC4/ASM20010869/Uga3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

___ \$ + RS ___ \$

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

FASTTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

unk certia

4/5 6250

Not Authorized
8/10/20
2/5 6250
5 days

VEHICLE No:SLR 5302J

1PC	REAR WINDSCREEN MOULDING	
1PC	REAR WINDSCREEN	
1PC	TAILGATE	953
1PC	TAILGATE OUTER GARNISH	
1PC	TAILGATE 'H' LOGO	
1PC	TAILGATE 'VEZEL' EMBLEM	
2PCS	TAILGATE REFLECTORS @\$364.60	
1PC	TAILGATE INNER LOCK	
1PC	TAILGATE LOCK STRIKER	
1PC	TAILGATE INNER TRIM BOARD	
1SET	TAILGATE INNER TRIM BOARD CLIPS	
1PC	TAILGATE INNER HANDLE HOLDER	
2PCS	TAILGATE DAMPERS @\$192.50	
1PC	TAILGATE WEATHERSTRIP	
1PC	REAR BUMPER	563.20
2PCS	REAR BUMPER SIDES @\$395.10	
2PCS	REAR BUMPER REFLECTORS @165.00	
1SET	REAR BUMPER CLIPS	
1PC	REAR BUMPER LOWER UNDER COVER	
1SET	REAR BUMPER LOWER UNDER COVER CLIPS	
2PCS	REAR BUMPER SIDE RETAINERS @\$45.00	
1PC	REAR END PANEL	
1PC	REAR END PANEL TOP GARNISH	
2PCS	TAILLAMPS @\$485.00	460.60
2PCS	TAILLAMP HOUSING PANELS @350.00	
1PC	REAR FLOOR PANEL	
1PC	REAR FLOOR PANEL TOP BOARD	
1PC	REAR FLOOR PANEL TOOLS SPONGE	
1PC	REAR LOCK SENSOR	
2PCS	REAR FENDERS @\$991.00	
2PCS	REAR FENDER INNER TRIMS @\$450.00	386.40
1PC	REAR EXHAUST	
1PC	REAR EXHAUST HEATSHIELD	
2PCS	REAR FENDER OUTER PROTECTORS @\$299.00	

neu	\$88.20	✓
11	\$1,650.00	X
badly 700	\$1,100.90	✓
neu	\$315.20	✓
neu	\$32.50	✓
neu	\$56.50	✓
MS sc	\$729.20	1pc
neu	\$181.90	✓
11	\$48.60	X
de/cue	\$368.20	✓
neu	\$50.00	✓
11	\$32.00	X
11	\$385.00	X
neu	\$199.00	✓
de	\$863.50	✓
11	\$790.20	X
MS sc	\$330.00	1pc
neu	\$50.00	✓
neu	\$312.00	✓
11	\$50.00	✓
11	\$90.00	X
neu	\$517.00	✓
neu	\$188.00	✓
MS cue	\$970.00	1pc
11	\$700.00	X
11	\$1,330.20	X
neu	\$326.50	✓
neu	\$688.00	✓
neu	\$295.00	✓
MS de	\$1,982.00	X
MS de	\$900.00	1pc
11	\$785.20	X
11	\$188.90	X
MS sc	\$598.00	1pc
	\$17,191.70	

20%

6909.50

S.NETT	
1SET	REAR BUMPER REVERSE SENSOR
1PC	REAR WINDSCREEN SEALANT
1PC	REAR LICENCE PLATE W/HOLDER
1SET	REAR FLOOR PANEL INSULATOR
1PC	REAR END PANEL SEALANT

shorted	\$280.00	200
neu	\$50.00	40
11	\$50.00	X
11	\$180.00	X
neu	\$50.00	✓

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$150.00	80
TO DISMANTLE & REFIX REAR EXHAUST	11 \$100.00	X
TO DISMANTLE & REFIX FUEL TANK	11 \$100.00	X
TO SPRAY RUST PROOFING	\$150.00	60
TO MOUNT VEHICLE ON CAR O-LINER	11 \$380.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	800
TO PUTTY & SPRAY PAINTING	\$1,800.00	900
TOTAL	\$22,581.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6909.80
20%

P-5527.84

S.N - 290.00

L - 2040.00

7857.84