

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0740/2020/NS
DATE	:	7-Oct-20
WIP	:	52050

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR CHIU ALLEN S
ADDRESS	:	103 WEST COAST VALE #23-17 SINGAPORE 127727
TELEPHONE	:	HP +65 97831380
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800088553-01
VEHICLE NO	:	SMC 9320 Y
MODEL CODE	:	AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR	:	27/7/2018
ENGINE NO	:	CVK 063249
CHASSIS NO	:	WAUZZZF56JA106384
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	5-Oct-20
PLACE OF ACCIDENT	:	WEST COAST VALE & WEST COAST HIGHWAY INTERSECTION


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 9320 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER. RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,500.00 1000	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT <i>fender</i>	\$ 1,650.00 1100	
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,252.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 9320 Y

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>del d</i>		\$ 2,251.00	✓
2 FRONT BUMPER FIXING PARTS <i>mea</i>		\$ 402.00	+
3 FRONT BUMPER GRILLE - CENTRE <i>mea</i>		\$ 194.00	+
4 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>mea</i>		\$ 225.00	+
5 FRONT BUMPER SPOILER ?		\$ 529.00	? ?
6 FRONT BUMPER AIR GUIDE - RH <i>mea</i>		\$ 62.00	x
7 RADIATOR GRILLE <i>mea</i>		\$ 2,300.00	x
8 ULTRASOUND SENSOR SUPPORT - LH / RH <i>mea</i> 2	2	\$ 102.00	x
9 RADIATOR GRILLE COVER - UPPER ?		\$ 187.00	?
10 FRONT BUMPER AIR GUIDE GRILLE - RH <i>mea</i>		\$ 468.00	+
11 FRONT PARKING AID SENSOR - OUTER <i>mea</i>		\$ 242.00	x
12 FRONT BUMPER CARRIER <i>mea</i>		\$ 795.00	x
13 FRONT BUMPER FOAM FILLER PIECE <i>mea</i>		\$ 123.00	x
14 FRONT BUMPER TOP COVER ?		\$ 126.00	?
15 FRONT BUMPER GUIDE SECTION - RH ?		\$ 36.00	?
16 CAUTION SIGN STICKER ?	NEC	\$ 14.00	?
17 AIRCON STICKER ?	NEC	\$ 8.00	?
18 LOCK CARRIER BRACKET <i>mea</i>		\$ 136.00	✓
19 FRONT BUMPER SUPPORT - LH / RH ?	2	\$ 56.00	?
20 HORN - RH LOW TONE <i>mea</i>		\$ 124.00	x
SUB TOTAL SPARE PARTS	:	\$ 8,380.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 9320 Y

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 SPRING SHACKLE - RH <i>ok</i>		\$ 29.00	<i>+</i>
22 FRONT FENDER - RH <i>Buckled</i>		\$ 1,048.00	<i>✓</i>
23 FRONT FENDER ATTACHMENT PARTS <i>ok</i>		\$ 53.00	<i>+</i>
24 FRONT FENDER CLOSING ELEMENT - RH <i>ok</i>		\$ 73.00	<i>+</i>
25 FRONT FENDER BRACKET - RH <i>?</i>		\$ 35.00	<i>?</i>
26 FRONT FENDER MIDDLE BRACKET <i>?</i>		\$ 35.00	<i>?</i>
27 FRONT FENDER BRACE - RH <i>?</i>		\$ 117.00	<i>?</i>
28 DEFORMATION ELEMENT BRACKET - RH <i>?</i>		\$ 49.00	<i>?</i>
29 WHEEL HOUSING LINER - RH <i>ok</i>		\$ 272.00	<i>+</i>
30 WHEEL HOUSING LINER ATTACHMENT PARTS <i>ok</i>		\$ 90.00	<i>+</i>
31 WHEEL SPOILER <i>ok</i>		\$ 73.00	<i>+</i>
32 WHEEL SPOILER TRIM <i>ok</i>		\$ 36.00	<i>+</i>
33 STONE CHIP GUARD - RH <i>ok</i>		\$ 50.00	<i>✓</i>
34 FRONT FENDER TRIM - RH <i>ok</i>		\$ 157.00	<i>✓</i>
35 FRONT ALUMINIUM RIM - RH <i>ok</i>		\$ 1,012.00	<i>+</i>
36 FENDER LEDGE COVER - INNER <i>?</i>		\$ 16.00	<i>?</i>
37 FENDER LEDGE COVER - OUTER <i>?</i>		\$ 35.00	<i>?</i>
38 FRONT NO PLATE <i>ok</i>	S/N	\$ 60.00	<i>+</i>
39 SUNDRIES <i>?</i>		\$ 250.00	<i>?</i>
TOTAL SPARE PARTS	:	\$ 11,870.00	
TOTAL LABOUR CHARGES	:	\$ 4,252.00	
GRAND TOTAL	:	\$ 16,122.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lj
08/10/20.

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT