

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBN5529L

at Workshop m/s

3MH

of

Insured:

SHC14222

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

\$8500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 3176

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBN5529L

Yr Regn:

10/18Type: M.Car / (M) Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha NMAX

c.c

155

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

34457

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH3SGH31000008517Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110-70-13

R:

130-70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TimSun

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

29/9/20

D.O.I.

9/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Nett 532x

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) ___ S + RS ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET

#04-00 & #06-00

IOB BUILDING

SINGAPORE 049711

ATTN: INDIA INTERNATIONAL INSURANCE P.L.

NO. : 36912

DATE : 30/09/2020

CLAIM NO. : 11625

POLICY NO. : MC/00833740

FROM : HASRIANAH

VEHICLE NO. : FBN5529L

MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - ACCIDENT	REPLACE	1.00	\$34.00	CUY 34.00
2	BOARD FOOTREST RH P/N: 59589 - ACCIDENT	REPLACE	1.00	\$52.00	CUY 52.00
3	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - ACCIDENT	REPLACE	1.00	\$222.00	CUY 222.00
4	EMBLEM (YAMAHA) LOGO P/N: 57069 - ACCIDENT	REPLACE	2.00	\$11.00	AM 22.00
5	HEADLAMP ASSY P/N: 58174 - ACCIDENT	REPLACE	1.00	\$308.00	CUY 308.00
6	LABOUR P/N: 06766	Supply/Install	6.00	\$63.00	250 378.00
7	LEVER BRAKE RH P/N: 58185 - ACCIDENT	REPLACE	1.00	\$18.00	SUR 18.00
8	MIRROR RH P/N: 58187 - ACCIDENT	REPLACE	1.00	\$37.00	CUY 37.00
9	PROTECTOR EXHAUST P/N: 58086 - ACCIDENT	REPLACE	1.00	\$38.00	CUY 38.00
10	RIVET P/N: 56583 - ACCIDENT	REPLACE	4.00	\$2.00	AM 8.00

*36912 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price		Amount
11	SPRAY PAINTING COVER TO CISCO WHITE - FRONT MUDGUARD, SIDE COVER UPPER & LOWER 411 & RH, PANEL	Spray	1.00	\$420.00	240	420.00
12	STICKER (CISCO) COWLING FRONT LH P/N: 58616	REPLACE	1.00	\$37.00	nm	37.00 ✓
13	STICKER (CISCO) COWLING FRONT RH P/N: 58617	REPLACE	1.00	\$37.00	nm	37.00 ✓
14	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$37.00	nm	37.00 ✓
15	TRANSPORT CHARGES-DELIVERY / COLLECTION P/N: 41525	✓	2.00	\$56.00	35	112.00

SUB TOTAL

\$1,760.00

GST @ 7 %

\$123.20

GRAND TOTAL (SGD)

\$1,883.20

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Insurance Surveyor's presence notify

the following:

- The repair technique spray painting
- The damaged part(s) during resurvey
- The repair is subject to confirmation
- The survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*36912 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO : 2002-1-0383
 ISO 9001 2015