

28 OCT 2020

Your Ref

: SHC1422Z

Our Ref

: TP/11625/FBN5529L/SHC1422Z

BY EMAIL & POST

India International Insurance Pte Ltd 64 Cecil Street #04-00 & 05-00 IOB Building Singapore 049711

ATTN: Motor Claims Dept

Dear Sir / Madam,

Accident Involving FBN5529L & SHC1422Z on 29/09/2020

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$1,	,392.18
2. Loss of Use (3 days x \$20)	\$	60.00
3. LTA Vehicle Insurance Search Fee	\$	7.45
TOTAL	\$1.	459.63

We attached our Tax Invoice and LTA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

Raymond Tan

Manager/Insurance Dept







INDIA INTERNATIONAL INSURANCE PTE LTD

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT20090451 Claimant Ref: FBN5529L

We/I,Ban Hock Hin Co. Pte Ltd ("the workshop") he with the appointed Surveyor of India International Insurance Pte Ltd of Surveyor) with respect to the amount claimed for S\$1,392.18 use/rental), S\$7.45 (search fee), vehicle no. FBN5529L that was on29/09/2020 (date) at NORTH CANAL RD X NEW BRIDGE RD vehicle). This is pursuant to the inspection conducted on09/10/2020 (date)	LKK Auto Co Grepair cost damaged pursuar (location) involvi	nsultants Pte Ltd (name st), S\$ 60.00 (loss of at to the accident which occurred on vehicle no. SHC1422Z (insured
We/I confirm that we/I are/am authorized by the owner BAN HO claimant") of vehicle no.FBN5529L to make the claim as set out in the athe matter on his/her behalf in a manner that we/I deem fit. We/I encloserty claimant".	bove paragraph a	nd we/l have full authority to settle
We/l further confirm that we/l will indemnify India International Insurance they will or have already incurred in the event that "the third party of further claim against the former for any loss and expenses suffered per of use pursuant to the damage to FBN5529L (vehicle no.) as a result of the damage to FBN5529L (vehicle no.)	laimant" after the ertaining to cost of	above said agreement lodges a
We/I confirm that the agreement reached above is in full and final s pursuant to the accident and that further this settlement is reached on basis.		
This agreement is subject to the application of Singapore law and the S dispute arising out of the same.	ingapore Courts ha	ive exclusive jurisdiction over any
We/I authorize you to pay the total amount of S\$ 1,459.63 to Ba	n Hock Hin C	Co. Pte Ltd_
Dated this day of Neverbor 20 20		
CLAIMANT:	WITNESS:	((LKK))
Signature: Signed by "the workshop" (with chop)	Signature:	Signed by appointed Surveyor
Name: Audrey Tan	Name:	LKK Auto Consultants Pte Ltd
NRIC: \$1438567C	NRIC:	199607198R
Address: 6 Vete Lane 4	Address:	51 Ubi Avenue 1
Sugapore 529900		#01-25 Paya Ubi Ind. Park S(408933)
Nationality:	Nationality:	
Occupation:	Occupation:	



MOTORCYCLE ACCESSORIES | SERVICE CENTRE MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

Customer:

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET #04-00 & #06-00 IOB BUILDING SINGAPORE 049711 MOTOR CLAIMS DEPT

CLAIM NO.

: 11625

POLICY NO. VEHICLE NO.

: MC/00833740 : FBN5529L

MAKE/MODEL

: YAM / NMAX155 ABS

TAX INVOICE

GST Reg No.: M2-0010542-7

Invoice No.

: LECR20038563-I11625

Invoice Date

: 23/10/2020

Payment Due Date : 22/11/2020

(Page 1 of 2)

S/N	<u>Description</u>	<u>Action</u>	Qty	Unit Price	<u>Amount</u>
1	BOARD FOOTREST RH	REPLACE	1	\$52.00 Disc %: 10%	\$46.80
2	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	REPLACE	1	\$222.00 Disc %: 10%	\$199.80
3	EMBLEM (YAMAHA) LOGO	REPLACE	2	\$11.00 Disc %: 10%	\$19.80
4	HEADLAMP ASSY	REPLACE	1	\$308.00 Disc %: 10%	\$277.20
5	LEVER BRAKE RH	REPLACE	1	\$18.00 Disc %: 10%	\$16.20
6	MIRROR RH	REPLACE	1	\$37.00 Disc %: 10%	\$33.30
7	PROTECTOR EXHAUST	REPLACE	1	\$38.00 Disc %: 10%	\$34.20
8	RIVET	REPLACE	4	\$2.00 Disc %: 10%	\$7.20
9	STICKER (CISCO) COWLING FRONT LH	REPLACE	1	\$37.00	\$37.00
10	STICKER (CISCO) COWLING FRONT RH	REPLACE	1	\$37.00	\$37.00
11	STICKER (CISCO) MUDGUARD FRONT	REPLACE	1	\$37.00	\$37.00
12	SPRAY PAINTING COVER TO CISCO WHITE	Spray	1	\$240.00	\$240.00
13	LABOUR	Supply/Install	1	\$250.00	\$250.00
14	TRANSPORT CHARGES-DELIVERY / COLLECTION		1	\$35.00	\$35.00
15	BELLY PAN	REPLACE	1	\$34.00 Disc %: 10%	\$30.60







Invoice No.: LECR20038563-I11625

(Page 2 of 2)

S/N	Description	Action	Qty	Unit Price	<u>Amount</u>
		SUB TOTAL			\$1,301.10
		GST @ 7 %			\$91.08
		GRAND TOTAL (SG	D)		\$1,392.18
Validi	ty: 30 days				

For & on Behalf of

BAN HOCK HIN CO PTE LTD

AN HOCK HIN COPIE LID

Printed by: RAYMOND







Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time :

08 Oct 2020 / 09:59:18

Receipt Date/Time:

08 Oct 2020 / 09:59:17

Tax Invoice/Receipt

Receipt No.: ITNET-00000-201008-000573

Previous Receipt No.:

r revious receipt No				
S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHC1422Z As at 29 Sep 2020/12:00:00 Insurance Co: INDIA INT'L INS PTE LTD 1 Insurance Enquiry - SHC1422Z				reas er euwerzwisse i prom e T okkowyk us zą
Enquiry Fee 20201008095603534066		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable Paid By 20201008095800141	Direct Debit: eN (Internet Ba		7.45 7.45
	Total	·		7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.