



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET

#04-00 & #06-00

IOB BUILDING

SINGAPORE 049711

ATTN: INDIA INTERNATIONAL INSURANCE P.L.

NO. : 36912

DATE : 30/09/2020

CLAIM NO. : 11625

POLICY NO. : MC/00833740

FROM : HASRIANAH

VEHICLE NO. : FBN5529L
MAKE/MODEL : YAM / NMAX155 ABS

*not actual
wku
2/12/2010
3 dy.
9/10/20
Zhu photo of the repair*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - ACCIDENT	REPLACE	1.00	\$34.00	<i>cu</i> 34.00
2	BOARD FOOTREST RH P/N: 59589 - ACCIDENT	REPLACE	1.00	\$52.00	<i>cu</i> 52.00
3	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - ACCIDENT	REPLACE	1.00	\$222.00	<i>cu</i> 222.00
4	EMBLEM (YAMAHA) LOGO P/N: 57069 - ACCIDENT	REPLACE	2.00	\$11.00	<i>nu</i> 22.00
5	HEADLAMP ASSY P/N: 58174 - ACCIDENT	REPLACE	1.00	\$308.00	<i>cu</i> 308.00
6	LABOUR P/N: 06766	Supply/Install	6.00	\$63.00	<i>250</i> 378.00
7	LEVER BRAKE RH P/N: 58185 - ACCIDENT	REPLACE	1.00	\$18.00	<i>sur</i> 18.00
8	MIRROR RH P/N: 58187 - ACCIDENT	REPLACE	1.00	\$37.00	<i>cu</i> 37.00
9	PROTECTOR EXHAUST P/N: 58086 - ACCIDENT	REPLACE	1.00	\$38.00	<i>cu</i> 38.00
10	RIVET P/N: 56583 - ACCIDENT	REPLACE	4.00	\$2.00	<i>nu</i> 8.00

*36912 *

bizSAFE₃



Address: No. 6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0363
SQ 5001 2015

S/N	Description	Action	Qty	Unit Price	Amount
11	SPRAY PAINTING COVER TO CISCO WHITE - FRONT MUDGUARD, SIDE COVER UPPER & LOWER LH & RH, PANEL	Spray	1.00	\$420.00	240 420.00
12	STICKER (CISCO) COWLING FRONT LH P/N: 58616	REPLACE	1.00	\$37.00	37.00
13	STICKER (CISCO) COWLING FRONT RH P/N: 58617	REPLACE	1.00	\$37.00	37.00
14	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$37.00	37.00
15	TRANSPORT CHARGES-DELIVERY / COLLECTION P/N: 41525		2.00	\$56.00	35 112.00

SUB TOTAL

\$1,760.00

GST @ 7 %

\$123.20

GRAND TOTAL (SGD)

\$1,883.20

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-739

wz

665-10

1701-10

*36912 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 8520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001:2015