

Our Job Ref No : 305427063Date 12/10/20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr STEVEVehicle Reg No. SHB2533KDate of Accident : 08/10/20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- GBG3478A

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$ 2383.40

(b) Labour Charges


\$1,101.00

Total for Part-By-Part Repair Cost\$ 3484.40

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%**Final Lumpsum Repair cost**3. Estimated normal period for repairs: 3 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : JUMANITel : 62148315Fax : 65468156Signature : Name : SteveDate : 17/10/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 16.10.2020

REPAIR ESTIMATE

Time: 10:37:02

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305427063
 REGN NO : SHB2533K
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 06.08.2020
 DATE/TIME IN : 08.10.2020 13:25
 ACCIDENT DATE : 08.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G	IONIQV4 COVER-FR BUMPER#	1	418.30	20.00	334.64
0002 04-01-0104-2935-G	IONIQV4 LAMP ASSY-HEAD RH	1	1,993.65	20.00	1,594.92
0003 04-01-0104-0573-G	IONIQVC PANEL-FENDER RH#	1	490.70	20.00	392.56
0004 04-01-0104-3913-G	IONIQVC EMBLEM-BLUE DRIVE	1	26.60	20.00	21.28
0005 04-01-0104-3918-G	IONIQVC BRACKET-FR BUMPER	1	28.00	20.00	22.40
0006 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60

SUB-TOTAL : 2,383.40

JOB NATURE

0000 PB	PANEL BEATING	640.00
0001 SP	SPRAYPAINT CHARGE	400.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0004 L	MERIMEN FEE	11.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 16.10.2020

REPAIR ESTIMATE

Time: 10:37:02

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305427063
REGN NO : SHB2533K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 06.08.2020
DATE/TIME IN : 08.10.2020 13:2
ACCIDENT DATE : 08.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,101.00

TOTAL : 3,484.40

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :