

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0748/2020/NS
DATE : 8-Oct-20
WIP : 52307

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR EE CHENG EN SAMUEL
ADDRESS : BLK 774 BEDOK RESERVOIR VIEW
#11-115
SINGAPORE 470774
TELEPHONE : HP +65 98711703
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070037067
VEHICLE NO : **SMS 8841 H**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 19/3/2020
ENGINE NO : CHZ C38868
CHASSIS NO : WAUZZZ8V1LA049446
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Oct-20
PLACE OF ACCIDENT : HOLLAND ROAD



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 8841 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT AND REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 560.00	✓
2	TO REMOVE AND REINSTALL LHS FRONT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG.	S/N \$ 1,800.00	X.
3	TO DISMANTLE AND RENEW LHS FRONT AND REAR DOOR. TO CUT OUT AND WELD LHS SILL PANEL AND LHS B-PILLAR. TO REPAIR LHS REAR FENDER, RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,500.00	1500
4	TO RESPRAY LHS FRONT DOOR AND LHS REAR DOOR, HINGES, LHS SILL PANEL, LHS B-PILLAR, DOOR ENTRANCES, DOOR HANDLES AND LHS REAR FENDER.	\$ 3,775.00	2200
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,827.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 8841 H

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 B-PILLAR AND SILL PANEL - LH <i>Repair</i>		\$ 1,971.00	X
2 FRONT DOOR - LH <i>Distorted</i>		\$ 2,267.00	✓
3 FRONT DOOR OUTER SEAL - LH <i>new</i>	NEC	\$ 159.00	✓
4 BONDING AGENT <i>?</i>	NEC	\$ 47.00	?
5 CLEANING SOLUTION <i>?</i>	NEC	\$ 65.00	?
6 FRONT DOOR ATTACHMENT PARTS <i>new</i>		\$ 238.00	X
7 FRONT DOOR CATCH <i>?</i>		\$ 104.00	?
8 REAR DOOR - LH <i>Distorted</i>		\$ 2,267.00	✓
9 REAR DOOR OUTER SEAL - LH <i>new</i>	NEC	\$ 159.00	✓
10 BONDING AGENT <i>new</i>	NEC	\$ 47.00	✓
11 CLEANING SOLUTION <i>new</i>	NEC	\$ 65.00	✓
12 REAR DOOR ATTACHMENT PARTS <i>new</i>		\$ 127.00	X
13 REAR DOOR CATCH <i>?</i>		\$ 93.00	?
14 DOOR HINGE HALF-UPPER PART - LH LOWER <i>new</i>		\$ 46.00	X
15 DOOR HINGE HALF-LOWER PART - LH LOWER <i>new</i>		\$ 46.00	X
16 WHEEL SPOILER - LH REAR <i>new</i>		\$ 35.00	X
17 STONE CHIP <i>?</i>	S/N	\$ 180.00	X
18 CAVITY WAX <i>new</i>	S/N	\$ 140.00	X
19 ACRYLIC SEALANT <i>new</i>	S/N	\$ 180.00	X
20 SUNDRIES <i>?</i>		\$ 350.00	?
TOTAL SPARE PARTS	:	\$ 8,586.00	
TOTAL LABOUR CHARGES	:	\$ 9,827.00	
GRAND TOTAL	:	\$ 18,413.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Adrian
08/10/20

the Authorised, 06 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT