

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 94888770

TP Chien.
Shirley.

ESTIMATE

Repair Code : CLM16482

Date in : 07/10/2020

Vehicle Num. : SLM4363R

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1763950/HRA2330634A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehnd</i>	1	755.40	✓ 755.40
REAR BUMPER REFLECTOR L/R <i>culd</i>	2	55.00	✓ 110.00
REAR BUMPER REINFORCEMENT <i>Set</i>	1	619.20	✓ 619.20
REAR BUMPER SIDE RETAINER L/R <i>m</i>	2	35.90	✓ 71.80
REAR BUMPER SPONGE <i>culd</i>	1	126.40	✓ 126.40
REAR BUMPER TOW HOOK COVER <i>xxxxx set</i>	1	16.80	✓ 16.80
REAR END PANEL <i>Detad</i>	1	482.60	✓ 482.60
REAR END PANEL ANTENNA SENSOR <i>culd</i>	1	285.10	98 285.10
REAR END PANEL INNER TOP GARNISH <i>Rehnd</i>	1	63.50	✓ 63.50
REAR TAILGATE 'QASHQAI' EMBLEM <i>from</i>	1	87.00	+ 87.00
REAR TAILGATE WEATHER STRIP <i>from</i>	1	158.70	+ 158.70

Subtotal before discount

2,776.50

Percentage discount 10%

277.65

Sub-total 1

2,498.85

REAR BUMPER CLIPS - SET <i>xx</i>	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR - SET <i>Daagd</i>	1	450.00	20 450.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>xx</i>	1	30.00	10 30.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 94888770

ESTIMATE

Repair Code : CLM16482
 Date in : 07/10/2020
 Vehicle Num. : SLM4363R
 Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
 Chassis/Eng# : SJNFEAJ11U1763950/HRA2330634A

Subtotal before discount	530.00
Percentage discount 0%	0.00
Sub-total 2	530.00
Parts-total	3,028.85

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,060.00
Parts & Labour Total	5,088.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer-generated document which requires no signature.***

page 2

Adrian Lj

L/S 12/10/20

05 Days

total: 3588.33

L/S: 2850