

AIG ASIA PACIFIC INS

FINALIZE

GST Ref. No: 20-0000274-Z

Vehicle No: SLB1845U
Chasis No: W0LGS5E53F1035109
Engine No: B1150435GKUX0098
Date of accident : 07/10/2020

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	1	FRT FENDER INNERSHIELD RH	\$ 154.00
2	10	FRT FENDER INNERSHIELD CLIP	\$ 65.00
3	1	FRT BUMPER	\$ 2,364.00
4	1	FRT BUMPER TOW COVER	\$ 156.00
5	1	FRT BUMPER LOWER CENTRE GRILLE	\$ 194.00
6	10	FRT BUMPER CLIP	\$ 65.00
7	1	FRT BUMPER TOP CENTRE RETAINER	\$ 172.00
8	1	FRT BUMPER SIDE RETAINER LH , SUPPORT	\$ 134.00
9	1	FRT BUMPER SIDE RETAINER RH , SUPPORT	\$ 134.00
10	1	FRT BUMPER BRACKET LH , GUIDE	\$ 120.00
11	1	FRT BUMPER BRACKET RH , GUIDE	\$ 120.00
12	1	FRT BUMPER SPONGE UPP	\$ 282.00
13	1	FRT BUMPER REINFORCEMENT IMPACT BAR UPP	\$ 646.00
14	1	FRT BUMPER FOG LAMP COVER RH	\$ 380.00
15	1	FRT BUMPER FOG LAMP RH	\$ 366.00
16	1	FRT BUMPER PARKING SENSOR	\$ 246.00
17	2	FRT BUMPER PARKING SENSOR SEAL	\$ 13.00
18	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	\$ 256.00
19	1	FRT GRILLE ASSY	\$ 1,141.00
20	1	RH HEADLAMP	\$ 1,528.00
21	1	LH HEADLAMP	\$ 1,528.00
22	1	A/C CONDENSER	\$ 1,498.00
23	1	TURBO INTAKECOOLER	\$ 1,047.00
24	1	AIR HOSE(TURBO TO INTAKECOOLER)	\$ 555.00
25	1	FRT INTAKE AIR DUCT(to resonator box)	\$ 415.00
26	1	RADIATOR	\$ 1,495.00
27	1	RADIATOR LOW BRACKET	\$ 34.00
28	1	RADIATOR FAN COWLING	\$ 835.00

Supplementary

1	1	FRT BUMPER REINFORCEMENT LOW		\$	384.00
2	1	ENGINE UNDER COVER RH		\$	116.00
3	1	FRT BUMPER REINFORCEMENT LOW BRACKET RH		\$	132.00

Total: \$ 16,575.00
Less 10%: \$ 1,657.50
Parts Total: \$ 14,917.50

Labour

No.			Price (SGD)
1		TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	\$ 1,950.00
2		CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA. FRT BUMPER , FRT BONNET , FRT FENDER RH , FRT FENDER LH , FRT SUPPORT PANEL , FRT DOOR RH , FRT DOOR LH	\$ 2,200.00
3		TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$ 120.00
4		TO REMOVE AND REFIT AIRCON CONDENSOR , VACUUM , REFILL AND CHECK AIR CON GAS SYSTEM	\$ 200.00
5		TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00

Labour Total : \$ 4,550.00

Other

No.			Price (SGD)
1	1	FRT NUMBER PLATE	
2	1	RADIATOR COOLANT	\$ 35.00
			\$ 80.00

Other Total : \$ 115.00

Total : \$ 19,582.50
Less Lump Sum 20% : \$ 3,916.50
Total Repair Cost : \$ 15,666.00
Round Down : \$ 15,600.00
Limit Repair Amount As Agree: \$ 10,500.00
Excess: \$ 500.00
GST (7%) : \$ 700.00
Grand Total : \$ 10,700.00

Yours Faithfully,

Kelvin Chew
Service Advisor
Tel: 68441985 Fax:68445185

Please check and finalize with me