

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Azlan, Syazairdina

Date: 14 Oct 2020

**Preliminary Advice**

Vehicle No	: SLB1845U	Accident Date	: 07/10/2020
Make	: OPEL INSIGNIA	Policy No.	: 2100503127
Assignment Date	: 09/10/2020	Excess	: S\$500.00
Date of Inspection	: 09/10/2020	Est. Duration of Repair	: 5
Inspection At	: FIRST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01 SOUTH WING SINGAPORE 415933		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,682.70
Revised Amount	:S\$	10,952.40
Check Items (Estimated)	:S\$	10,852.20
Total	:S\$	21,804.60

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	47,157.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,843.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Margin for repair is \$ 10,843.00. Repairer able to repair the vehicle not exceeding \$ 10,500.00 on lump sum basis.