

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 8/10/2020
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

Owner : YANG SU
NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate Number : 5118783702

Accident Date :

Vehicle Number : SKV2225J

Make & Model : SUBARU FORESTER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

acknowledged by Repairer

Signature:

7/10/2020

JFISJSKCSFG056017

TPALG.
1chanha.

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1	BONNET <i>Dented.</i>	\$ 880.00	✓
1	BONNET CHROME <i>new</i>	\$ 120.00	+
1	BONNET LOGO <i>new</i>	\$ 65.60	+
1	BONNET GRILLE LOWER <i>new</i>	\$ 118.00	+
1	BONNET GRILLE UPPER	\$ 226.00	+
1	RH HEADLAMP <i>cracked</i>	\$ 2,400.00	✓
1	RH HEADLAMP NOZZEL MOTOR <i>damaged</i>	\$ 150.60	✓
1	RH HEADLAMP NOZZEL COVER <i>missing</i>	\$ 65.40	✓
1	RH HEADLAMP PANEL <i>distorted</i>	\$ 165.00	✓
1	RH FRONT FENDER <i>distorted</i>	\$ 350.00	✓
1	RH FRONT FENDER SHILD <i>torn</i>	\$ 185.00	✓
1	RH FRONT LOWER ARM	\$ 550.00	+
1	RH FRONT KNOCKLE ARM	\$ 550.00	+
1	RH FRONT KNOCKLE ARM BEARING	\$ 350.00	+
1	RH FROTN SHOCK ABSORBER	\$ 450.00	+
1	AIR DUCT <i>new</i>	\$ 95.00	+
1	RH WHEEL ARCH <i>new</i>	\$ 850.00	+
1	RH WHEEL ARCH PANEL <i>new</i>	\$ 950.00	+
1	RH WHEEL ARCH PANEL INNER COVER <i>new</i>	\$ 250.00	+
1	FRONT BUMPER <i>Distorted</i>	\$ 650.60	+
1	FRONT BUMPER INNER GARNISH <i>new</i>	\$ 150.80	+
1	RH FRONT BUMPER RETAINER <i>damaged</i>	\$ 16.50	+
1	LH FRONT BUMPER RETAINER <i>new</i>	\$ 16.50	+
1	FRONT BUMPER FOG LAMP COVER RH <i>damaged</i>	\$ 25.00	✓
1	RH FRONT BUMPER FOG LAMP <i>cracked</i>	\$ 270.00	✓
1	RH FRONT BUMPER TOWING COVER <i>damaged</i>	\$ 25.00	✓
1	<i>Air Clearer</i> <i>cracked</i>	\$ 110.00	✓
1	FRONT BUMPER REINFORCEMENT <i>Bent</i>	\$ 350.00	✓
1	FRONT BUMPER SPONGE <i>new</i>	\$ 220.00	+
1	FRONT SUPPORT PANEL <i>repair</i>	\$ 580.00	+
1	FRONT SUPPORT PANEL TOP GARNISH <i>damaged</i>	\$ 130.00	✓
1	RADIATOR	\$ 792.00	+
1	AIR CON CONDENSER	\$ 680.00	+
1	AIR CON FAN BLADE	\$ 150.00	+
1	AIR CON FAN MOTOR	\$ 550.00	+

1	AIR CON FAN COWLING	He nr	\$	150.00	X
1	REAR BUMPER	Distorted	\$	650.00	✓
1	REAR BUMPER TOWING COVER	Missing	\$	25.00	✓
1	REAR BUMPER SPOILER	Distorted	\$	1,800.00	8w(SN)
1	REAR BUMPER RETAINER RH	Dang	\$	25.00	✓
1	REAR BUMPER RETAINER LH	Neu	\$	25.00	+
10	REAR BUMPER CLIPS	Neu	\$	50.00	+
1	REAR BUMPER LOWER GARNISH	He nr	\$	350.00	+
1	REAR BUMPER REFLECTOR RH	crackd	\$	35.00	+
1	REAR BUMPER REFLECTOR LH	He nr	\$	35.00	+
1	REAR BUMPER REINFORCEMENT	Best	\$	450.00	✓
1	RH REAR FENDER	Buckled	\$	960.00	✓
1	RH REAR FENDER INNER SHIELD	Deformed	\$	250.00	✓
1	TAILGATE	Distorted	\$	1,350.40	✓
1	TAILGATE WINDSCREEN	shattered	\$	950.00	✓
1	TAILGATE WINDSCREEN MOULDING	nr	\$	135.00	✓
1	TAILGATE EMBLEM "SUBARU"	3 pr	\$	85.00	✓
1	TAILGATE EMBLEM "FORSTER"		\$	75.00	✓
1	TAILGATE EMBLEM "AWD"		\$	35.00	✓
1	TAILGATE LOGO	nr	\$	95.00	✓
1	TAILGATE LOCK	Dang	\$	350.00	✓
1	TAILGATE TOP GARNISH	crackd	\$	215.00	✓
1	TAILGATE INNER TRIM BOARD	Deformed	\$	250.00	✓
1	LH TAILLAMP	He nr	\$	450.00	+
1	RH TAILALMP	crackd	\$	450.00	+
1	REAR END PANEL	Distorted	\$	450.00	✓
1	REAR END PANEL TOP GARNISH	Deformed	\$	120.00	✓
1	SPARE TYRE PANEL	Reps	\$	550.00	+
1	EXHAUST MUFFLER	Deformed	\$	850.00	✓
1	EXHAUST CHROME	Best	\$	120.00	✓

Sub Total	\$	24,822.40
DISCOUNT 25% on Parts	\$	6,205.60
Total	\$	18,616.80

Special Nett Item

1	RH FRONT SPORT RIM	3 pr nr	\$	640.00	X
1	RH FRONT TYRE		\$	450.00	+
1	REAR BUMPER CLIPS	nr	\$	50.00	30
1	REAR BUMPER SENSOR	Neu	\$	350.00	+
1	RH FRONT TYRE	Neu	\$	150.00	+
1	REAR WINDSCREEN SEALANT	nr	\$	100.00	60
1	TAILGATE WIPER BLADE	ut	\$	56.00	✓
10	RH FRONT FENDER INNER SHIELD CLIPS	nr	\$	50.00	30
10	RH REAR FENDER INNER SHIELD CLIPS	nr	\$	50.00	30
10	AIR DUCT CLIPS	Neu	\$	60.00	+
1	LH REAR BUMPER REVERSE SENSOR	Dang	\$	350.00	20
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS	nr	\$	50.00	20
10	FRONT BUMPER CLIPS	nr	\$	50.00	30
			\$	2,406.00	

LABOUR CHARGE

1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS		\$	2,500.00	1800
1	TO SPRAY PAINT ON ACCIDENT AREAS		\$	1,800.00	1600
1	TO REMOVE AND REFIT TAILATE COMPARTMENT		\$	150.00	80
1	TO CONDUCT WHEEL ALIGNMENT		\$	100.00	X
1	TO REMOVE AND REFIT UNDERCARRIAGE		\$	250.00	X
1	TO REMOVE AND REFIT REAR WINDSCREEN		\$	150.00	120
1	TO CHECK WATER LEAKING		\$	100.00	X
1	TO RUST PROOFING ACCIDENT AREAS		\$	150.00	100
1	TO REMOVE AND REFIT EXHASUT MUFFLER		\$	250.00	80
	Sub Total		\$	5,450.00	
			\$	26,472.80	

Grand Total

13748.5
108888
S.N: 8W

456.

3780

total: 16034.80

4/s: 12.8K

14 Days