



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:	SMG 5414 R
MAKE & MODEL:	MAZDA 3
MILEAGE:	
TYRE:	
CHASSIS NUM:	

ATTN:				
NO.	DESCRIPTION - PARTS	QTY	PRICE	
1	REAR WINDSCREEN MOULDING X nn	1	\$ 351.00	
2	TAILGATE X nn	1	\$ 1452.00	
3	TAILGATE WIPER X nn	1	\$ 201.00	
4	TAILGATE WIPER MOTOR X nn	1	\$ 395.00	
5	TAILGATE WIPER GARNISH X nn	1	\$ 120.00	
6	TAILGATE LOGO (MAZDA) X nn	1	\$ 110.00	
7	TAILGATE EMBLEM (MAZDA) X nn	1	\$ 105.00	
8	TAILGATE EMBLEM (SKYACTIVE) X nn	1	\$ 97.00	
9	TAILGATE LAMP (L+R) X nn	2	\$ 1172.00	
10	TAILGATE HANDLE X nn	1	\$ 305.00	
11	TAILGATE HANDLE SWITCH X nn	1	\$ 255.00	
12	TAILGATE CARPLATE LAMP X nn	2	\$ 156.00	
13	TAILGATE LOCK X nn	1	\$ 321.00	
14	TAILGATE LOCK COVER X nn	1	\$ 117.00	
15	TAILGATE LOCK CATCH X nn	1	\$ 112.00	
16	TAILGATE INNER BOARD X nn	1	\$ 625.00	
17	TAILGATE DAMPER (L+R) X nn	2	\$ 640.00	
18	TAILGATE HINGE (L+R) X nn	2	\$ 478.00	
19	TAILGATE WEATHERSTRIP X nn	1	\$ 396.00	
20	TAIL LAMP (L+R) X nn	2	\$ 1,876.00	
21	TAIL LAMP PANEL (L+R) X nn	2	\$ 978.00	
22	REAR BUMPER / 00 949 ✓	1	\$ 1,306.00	
23	REAR BUMPER RETAINER (L+R) / BR 160 ✓	2	\$ 428.00	
24	REAR BUMPER REINFORCEMENT BAR ? / BT 573.30 ✓	1	\$ 879.00	
25	REAR BUMPER BRACKET (L+R) X nn	2	\$ 596.00	
26	REAR BUMPER BEAM X nn	1	\$ 416.00	
27	REAR BUMPER SPONGE ? X nn	1	NIL.	
28	REAR BUMPER REVERSE SENSOR SET ? / SLVD 319 ✓ \$488.	12	\$ 976.00	
29	REAR BUMPER REFLECTOR (L+R) (LH) ? / BR 50.40 ✓ \$289	12	\$ 578.00	
30	REAR BUMPER TOW COVER (L+R) (LH) ? X nn	12	\$ 99.00	
31	REAR BUMPER LOWER / CHT 376 ✓	2	\$ 671.00	
32	REAR BUMPER EXHAUST COVER (L+R) X nn	2	NIL	
33	REAR BUMPER UNDERCOVER X nn	1	\$ 671.00	
34	REAR FENDER (L+R) X nn	2	\$ 4768.00	
35	REAR FENDER INNER TRIM (L+R) X nn	2	\$ 1,878.00	
36	REAR FENDER AIR VENT (L+R) X nn	2	\$ 144.00	
37	REAR FENDER COWLING (L+R) X nn	2	\$ 286.00	
38	END PANEL X R	1	\$ 1,079.00	
39	END PANEL TOP GARNISH X nn	1	\$ 416.00	
40	REAR SMART LOCK ANTENNA ? / BR 210.20 ✓	1	\$ 1,042.00	

41	FLOOR PANEL	X nn		1	\$1,711.00	
42	FLOOR PANEL TOP BOARD W MAT	X nn		1	\$ 201.00	
43	EXHAUST PIPE	X nn		1	\$999.00	
44	EXHAUST GASKET	X nn		1	\$74.00	
45	EXHAUST BRACKET (L+R)	X nn		2	\$104.00	
46	EXHAUST HEAT SHIELD	X nn	2637.90	1	\$329.00	
			-20%			
			2110.32			
			SUBTOTAL		\$ -	
			LESS 10%		\$ -	
			PARTS TOTAL		\$ -	
			SPECIAL NETT	QTY	PRICE	
1	REAR WINDSCREEN SEALANT	nn		1	\$ 120.00	X
2	TAILGATE INNER BOARD CLIPS	nn		10	\$ 100.00	X
3	REVERSE CAMERA	nn		1	\$ 950.00	X
4	REAR CARPLATE	nn		1	\$ 120.00	X
5	REAR CARPLATE FRAME	nn		1	\$ 120.00	X
6	TAIL LAMP CLIPS	nn		4	\$ 80.00	X
7	REAR BUMPER CLIPS	nrc		10	\$ 100.00	30
8	REAR FENDER SEALANT	nn		1	\$ 120.00	X
9	REAR FENDER INNER TRIM CLIPS	nn		20	\$ 200.00	X
10	REAR FENDER COWLING CLIPS	nn		20	\$ 200.00	X
11	END PANEL SEALANT	nn		1	\$ 120.00	X
12	END PANEL TOP GARNISH CLIPS	nn		10	\$ 100.00	X
13	FLOOR PANEL SEALANT	30 nn		1	\$ 120.00	X
			SPECIAL NETT TOTAL		\$ 2,450.00	
			LABOUR	QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	400		1	\$ 3,600.00	300
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA			1	\$ 3,000.00	400
3	TO RUST PROOF ACCIDENT AFFECTED AREA			1	\$ 600.00	30
4	TO RNR REAR WINDSCREEN			1	\$ 400.00	X
5	TO RNR REAR BOOT MECHANISM			1	\$ 400.00	X
6	TO RNR REAR LUGGAGE COMPARTMENT			1	\$ 400.00	X
7	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS			1	\$ 1,200.00	X
8	TO RNR REVERSE SENSOR & CHECK FUNCTION.			1	\$ 150.00	30
9	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS			1	\$ 350.00	X
10	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION			1	\$ 150.00	X
11	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.			1	\$ 800.00	X
12	TO DO WATER LEAK TEST .	890		1	\$ 120.00	30
13	TO RNR FUEL TANK TO ASSIST WORK LOAD			1	\$ 300.00	X
			TOTAL		\$ 11,470.00	
			GRAND TOTAL COST		\$ 13,920.00	
			P - 2110.32			
			N - 30			
			L - 890			
			= 3030.32			
			L/S - 2424.25			
			= 2400			

Stere (LKK) wtl Puzl
 9/10/20, 11.00am
 3 hrs
 L/S
 M AL SM