



Exceptional Journeys

Surveyor : Taufikh - LKK  
Ins Company : AIG  
DOA : 08/10/2020  
CSE : Don  
Date of Survey : 09/10/2020

VEHICLE NO : SLB6106L  
MODEL : MIT/ ASX 2.0 CVT 2WD  
WIP : 58323

Material	:	\$	6,223.91
Labour	:	\$	5,515.00
Sub-Total	:	\$	11,738.91
Less Excess	:	\$	600.00
Total	:	\$	11,138.91
GST 7%	:	\$	779.72
Grand Total	:	\$	11,918.63
Finalise By/Date	:	JoJo dtd 03/11/2020	

Email :

REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 9 WORKING DAYS + 4 Days ( 2 ) Weekends  
+          Days (          ) Public Holiday  
+ 1 Survey - 09/10/2020 - Fri  
TOTAL DAYS REPAIR TOOK = 14

TP Claim \_\_\_\_\_

Claim GIA / LTA fee \_\_\_\_\_

Claim Loss  Use  Rental

Claim Medical Fee / Others \_\_\_\_\_

Third Party Report \_\_\_\_\_



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  13/10/2020	Cust No/Name	KCV14451/TAN JACK WEI (CHEN YIWEI)
	Reg No/Reg Date	SLB6106L / 15/04/2016
	Date In/Mileage	26/10/2020/ 82364
	Chassis/Package	JMFXTGA2WFZC10585 /DC17PP
	Engine No	4B11QY7722
	Make/Model	MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	03/11/2020/ 09:20	BLD	881 / Jojo Cheng	58323

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR TAILGATE, RR BUMPER, CUT/WELD RR END PANEL, REPAIR FLOOR PANEL				✓ 1800.00
E PNT88000 REMOVE AND TRANSFER REAR TAILGATE AND OTHERS ATTACHMENT NEW PANEL				✓ 120.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				✓ 60.00
E PNT88000 REMOVE AND INSTALL REAR WINDSCREEN GLASS				✓ 240.00
M SUNDRY SUPPLY REAR WINDSCREEN SEALANT				✓ 80.00
E PNT98000 SPRAY PAINT RR FLOOR PANEL, RR END PANEL, RR BUMPER, RR TAILGATE AND AFFECTED PORTION				✓ 1400.00
M SUNDRY SUPPLY C&C LOGO				✓ 40.00
M SUNDRY APPLY BODY SEALANT				✓ 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30.00
M SUNDRY PERFORM RUST PREVENTION				✓ 40.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 120.00
A 30000001 RENEW REAR EXHASUT SYSTEM				? 225.00
M SUNDRY SUNDRIES				✓ 20.00
S SPECIALISTJOB SUPPLY ONE SET OF REVERSE SENSOR				✓ 220.00
A 54900099 RENEW REAR CROSSMEMBER - Supp				225.00

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV14451/TAN JACK WEI (CHEN YIWEI)
13/10/2020	Reg No/Reg Date	SLB6106L / 15/04/2016
	Date In/Mileage	26/10/2020/ 82364
	Chassis/Package	JMFXTGA2WFZC10585 /DC17PP
	Engine No	4B11QY7722
	Make/Model	MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX0008	Credit	03/11/2020/ 09:20	BLD	881 / Jojo Cheng	58323		
Description of Goods / Services							
				Qty	Unit Price	Disc%	Amount
B WHEELALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment - <i>supp</i>							
X EXC							-600.00
EXCESS							
E PNT88000							225.00
ADDITIONAL REPAIR REAR CHASSIS MEMBER - <i>supp</i>							
E PNT98000							350.00
ADDITIONAL PAINT WORK RH REAR CHASSIS - <i>supp</i>							
E PNT88000							120.00
ADDITIONAL REMOVE AND INSTALL REAR BOOT COMPARTMENT TO FACILITATE REPAIR WORK - <i>supp</i>							
X W/STRIP, TAILGATE OPENING				1.00	194.00	23.00	✓149.38
X PANEL ASSY, TAILGATE				1.00	1130.00	23.00	✓870.10
X DAM, TAILGATE, LWR				1.00	27.00	23.00	✓20.79
X LATCH, TAILGATE				1.00	383.00	23.00	✓294.91
X MARK, THREE-DIA				1.00	69.00	23.00	✓53.13
X MARK, ASX				1.00	56.00	23.00	✓43.12
X PANEL, RR END				1.00	259.00	23.00	✓199.43
X PANEL, RR END, INR RH				1.00	28.00	23.00	✓21.56
X TRIM, RR END				1.00	123.00	23.00	✓94.71
X REINFORCEMENT, RR BUMPER				1.00	233.00	23.00	✓179.41
X FACE, RR BUMPER				1.00	885.00	23.00	✓681.45
X COVER, RR FOG LAMP				1.00	44.00	23.00	✓33.88
X MOULDING, RR WHEEL ARCH, LH				1.00	132.00	23.00	✓101.64
X PROT, UNDER RR FLOOR HEAT				1.00	93.00	23.00	✓71.61
X MUFFLER, EXHAUST MAIN				1.00	861.00	23.00	✓662.97
X PIPE, EXHAUST, CTR				1.00	2068.00	23.00	✓1592.36
X BUZZER, KEYLESS OPERATIO, RR				1.00	91.00	23.00	70.07
X GASKET, CATALYTIC CONVERTER				1.00	11.00	23.00	8.47
X BOX, CARGO FLOOR				1.00	182.00	23.00	140.14
X CROSSMEMBER, RR SUSP				1.00	1184.00	23.00	911.68
X SILENCER, FLOOR				1.00	14.00	23.00	✓10.78
X COVER, RR BUMPER - <i>supp</i>				1.00	16.00	23.00	12.32

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



**SUPPLEMENTARY**

INSURANCE CO : AIG ASIA PACIFIC INSURANCE PTE LTD

REGISTRATION NO : SLB6106L

S/N	Description	Qty	Unit Price	Disc%	Amount
<b>LABOUR</b>					
1	RENEW REAR CROSSMEMBER	1.00	225.00	0.00	225.00
2	TO CONFUCT COMPUTERIZE FULL WHEEL ALIGNMENT	1.00	120.00	0.00	120.00
3	REPAIR REAR CHASSIS MEMBER	1.00	225.00	0.00	225.00
4	SPARY PAINT RH REAR CHASSIS	1.00	350.00	0.00	350.00
5	R/I REAR BOOT COMPARTMENT TO FACILITATE	1.00	120.00	0.00	120.00
<b>PARTS</b>					
1	BUZZER, KEYLESS OPERATIO, RR	1.00	91.00	23.00	70.07
2	GASKET, CATALYTIC CONVERTER	1.00	11.00	23.00	8.47
3	BOX, CARGO FLOOR	1.00	182.00	23.00	140.14
4	CROSSMEMBER, RR SUSP	1.00	1,184.00	23.00	911.68
5	COVER, RR BUMPER	1.00	16.00	23.00	12.32
<b>Total</b>					<b>2,182.68</b>
7 % GST					152.79
<b>Grand Total</b>					<b><u>2,335.47</u></b>

Thank You.

Yours faithfully,

**CYCLE & CARRIAGE AUTOMOTIVE PTE LTD**

JoJo Cheng

Customer Service

Tel : +65 6568 4554

CAR NO: SLB 6106L

WIP: 58323

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Reinforcement Rear Bumper	? / SUPP	bt		
2	Buzzer	? / SUPP	cu		
3	Rear Wire Harness	? / SUPP	tu		
4	Protector Under RR. Floor Heert	? / SUPP	neu		
5	Muffler, Exhaust Man.	? / SUPP	bt		
6	Silencer Pad - Rear floor	? / SUPP	neu		
7	COVER RR Fog lamp	? / SUPP	bt		64108704XA
8	BOX cargo FLOOR L+R	? / SUPP	cu		7646A 452
9	Gasket exhaust PIPE	? / SUPP	neu		MN110644
10	Crossmember RR SUSP	? / SUPP	bt		4100A092
11	R/I Rear Compartment facilitate repair	? / SUPP	\$120 ✓		
12	Repair RH rear chassis	? / SUPP	\$225 ✓		
13	R/I crossmember RR susp	? / SUPP	\$225 ✓		
14	Paintwork RH rear chassis	? / SUPP	\$350 ✓		
15	ton in cover - Rear (missing)	? / SUPP	Sub 14/10		
16		? / SUPP			
17	Centre exhaust pipe	? / SUPP	bt ✓		1570CS97.
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
20/12	A' Nag Chom Jan

MODEL: ASX 2.0

SURVEYOR: Tawfikh @ LKK

Work Order: R001228  
 License: SLB 6106 L  
 Technician: 106 WENG SOON  
 Mileage: 82364  
 Date: 31.10.20 11:33

Mitsubishi : ASX/RVR : Front Wheel Drive : 2010-

Front : Left

Actual	Before	Specified Range
0°27'	0°24'	-0°15' 0°45'
2°41'	2°41'	2°10' 3°10'
0°04'	-0°05'*	-0°02' 0°08'
11°38'	11°42'	11°30' 14°30'
12°05'	12°05'	11°15' 15°15'

Front : Right

Actual	Before	Specified Range
0°07'	0°17'	-0°15' 0°45'
3°06'	3°06'	2°10' 3°10'
0°04'	0°12'*	-0°02' 0°08'
12°23'	12°13'	11°30' 14°30'
12°30'	12°30'	11°15' 15°15'

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

Front

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
0°20'	0°07'	-0°30' 0°30'
-0°25'	-0°25'	-0°30' 0°30'
-0°45'	-0°32'	
0°08'	0°07'	-0°04' 0°16'
		-2°00' 2°00'

Rear : Left

Actual	Before	Specified Range
-0°52'	-1°00'*	-0°55' 0°05'
0°06'	0°06'	0°01' 0°16'

Rear : Right

Actual	Before	Specified Range
-0°42'	-0°36'	-0°55' 0°05'
0°07'	0°02'	0°01' 0°16'

Camber  
 Toe

Rear

Cross Camber  
 Total Toe  
 Thrust Angle

Actual	Before	Specified Range
-0°10'	-0°24'	-0°30' 0°30'
0°13'	0°09'	0°01' 0°31'
-0°01'	0°02'	

All DTCs

2020.10.27

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	GA2W 2015MY

SLB 6106 ↓

→ M.U.T. III Diag. chk.

↳ Read DTC only. Before

All DTCs

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81040000		No DTCs	
Air Conditioner	AC_80080006		No DTCs	
ETACS (Can see P/N on ECU body)	ETACS_83040900	B16A2 B16A4	Turn signal(LH) bulb outage Turn signal(RH) bulb outage	Stored Stored
Meter	MTR_84084000		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
LIN (Can see P/N on ECU body)	ETACS_83040900		Non-target System	
KOS/IMMO/Keyless/TPMS (IMMOBI & KOS)	KOS_WCM_8A880001_08MY	B240C	Tail gate antenna(outdoor) open	Stored
OSS	OSS_95040000		No DTCs	