

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	09 Oct 2020 12:18	Clm Veh Model Changed	(203482) MITSUBISHI ASX 2.0 (A).	[] Merimen Administrator
2	09 Oct 2020 12:18	Clm Created	Reg No: SLB6106L. Policy No: 2100459741-04. Acct Date: 2020/10/08. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MCC620088277	[I] Merimen Administrator
3	09 Oct 2020 15:20	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	09 Oct 2020 15:20	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	09 Oct 2020 15:20	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	09 Oct 2020 15:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/10/20	[A] LEE SU THING
7	09 Oct 2020 15:20	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	09 Oct 2020 15:20	Clm Registration Modified	Rep:1137->200066.	[A] LEE SU THING
9	09 Oct 2020 15:20	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] LEE SU THING
10	12 Oct 2020 09:49	Clm Registration Modified	Pol No:2100459741-04->2100459741.	[I] Lim, Sheng Yang
11	12 Oct 2020 11:31	Adj Rpt Initiated		[A] SHIAU CHAN
12	12 Oct 2020 11:31	Clm Dtl Modified	JPJ Reg. Date: -> 2016/04/15.	[A] SHIAU CHAN
13	12 Oct 2020 11:31	Clm Details Notified		[A] SHIAU CHAN
14	12 Oct 2020 11:41	Clm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Nadaraja, Deeban
15	12 Oct 2020 11:41	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
16	12 Oct 2020 12:13	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/10/20	[A] SHIAU CHAN
17	12 Oct 2020 12:14	Adj Mandate Request	Cur Req:10326.71:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] SHIAU CHAN
18	12 Oct 2020 13:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/10/20. Mandate Remarks: Not authorize. Labour to replace Rr End Panel & repair floor Panel \$1,800 to revise update Parts- Cover, Rr Fog Lamp & Moulding, Rr Wheel Arch, L H & Panel, Rr End, Inr RH further damaged photo	[I] Ng, Thaddaeus-HC
19	12 Oct 2020 13:33	Adj Mandate Set	Maintained:Not authorize. Labour to replace Rr End Panel & repair floor Panel \$1,800 to revise update Parts- Cover, Rr Fog Lamp & Moulding, Rr Wheel Arch, LH & Panel, Rr End, Inr RH further damaged photo TBC	[I] Ng, Thaddaeus-HC
20	12 Oct 2020 16:13	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/10/20	[A] SHIAU CHAN
21	12 Oct 2020 16:14	Adj Mandate Request	Cur Req:9876.71:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
22	13 Oct 2020 08:56	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2020/10/20. Mandate Remarks: Repair day at 07 repair days to update. Check, Supplementary & B4 Paint to update.	[I] Ng, Thaddaeus-HC
23	13 Oct 2020 08:56	Adj Mandate Set	Approved:6993.51:Repair day at 07 repair days to update. Check, Supplementary & B4 Paint to update.	[I] Ng, Thaddaeus-HC

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name	Ref 1	Ref 2	Amount
-------------	-----------	-----------	----------	----------	---------	-------	-------	--------

					(Branch)		
2607939	12 Oct 2020 11:31:40	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLB6106L	11.00