

威利摩哆

**WEI LEE MOTOR WORKS**

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

09,OCT 2020

AIG Asia Pacific Insurance PL  
78 Shenton Way #07-16  
AIG Building  
S 079120

*Not Authorized  
11 Sep @ 5900:00 Max  
Return After Paint*

Attn: Motor claim dept-3<sup>rd</sup> party claim  
Claiming against your insured vehicle no: GBE3962D  
Accident involving vehicle no: SMU6499R/GBE3962D  
DOA: 07/10/2020 AT Along Joo Chiat Rd Nr unit 333

Dear officer incharge  
Re: estimate cost of repair for vehicle no: SMU6499R  
To supply--

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*6 days*

Description	Qty	Amount
Rh front door <i>881.90</i>	1 <i>Rh</i>	881.90 ✓
Front door hinge @78.20	2 <i>R</i>	156.40 X
Front door checker	1 <i>Sc</i>	138.20 X
Front fender,Rh	1 <i>Rh</i>	602.40 ✓
Fender cowling	1 <i>Diy</i>	236.70 ✓
Cowling clip	<i>Ne</i>	38.00 ✓
Fender triangle garnish	1 <i>MRT</i>	76.20 ✓
Side mirror,Rh	1 <i>CM</i>	980.00 ✓
Mirror cover	1 <i>Ne</i>	83.20 ✓
Bonnet <i>862.90</i>	1 <i>Bu</i>	978.20 ✓
Front bumper	1 <i>Bu</i>	459.75 ✓
Bumper retainer,Rh	1 <i>Diy</i>	54.50 ✓
Bumper clip	<i>Ne</i>	42.00 ✓
Headlamp,Rh	1 <i>CM</i>	525.30 ✓
Front Rh absorber	1 <i>QV Rh</i>	356.90 ✓
Knuckle arm,Rh	1 <i>Rh</i>	441.40 ✓
Drive shaft,Rh <i>1410.60</i>	1 <i>Rh</i>	1,633.40 ✓
Wheel hub	1 <i>Rh</i>	197.80 ✓
Bearing	1 <i>Ne</i>	119.40 ✓
Lower arm,Rh	1 <i>Diy</i>	326.30 ✓
Rh tyre	1 <i>Sc</i>	140.00 X
Rim,Rh <i>258</i>	1 <i>Rd</i>	260.00 ✓
Parts		8,727.95
Parts less 25%		2,181.98
		6,545.96

1  
1  
1  
1  
1

Vehicle no: SMU6499R

To remove/transfer door glass, doorboard, power mechanism to new door.	120.00	601
To remove damaged parts and attachments		
Straighten chassis where necessary		
Repair/reshape all damaged panel/areas		
Replace/align all parts into position	1,000.00	7001
To repair/replace undercarriage parts	400.00	2001
Computer alignment	80.00	801
To spray paint	1,200.00	8501
	-----	
	9,345.96	