

(08/11/13) \ wef

ASS. REC. BY: Marcus

REF:

CCG/CY120010913/4ka3

ASSIGNMENT

From:

Date:

Veh No:

SBA5985

Yr Regn:

1216

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

CA /

To Inspect Vehicle No:

SBA5985

Make:

Toyota wellfire c.c 3456

at Workshop m/s

7 knee

Colour

white

A/C:

Insured / Std / NI / NA

of

Sp. Reading

121358

T/Radio:

Insured / Std / NI / NA

Insured:

GRE 480914

Eng/No:

Policy No.

C/No:

AGH/300005617

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

R:

255/40 R20

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Bal. or Market Value:

128k.

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

6

days

Res.: Yes or No

D.O.A.

8/10/20

D.O.I.

9/10/20

Lum Sum:

20

%

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

057N

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 17k.

LTA 71643

15/10/20 confirmed 2/5 \$8600 with AH hai

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

) __ S + RS, __ SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

LEE BROTHERS AUTOMOTIVE PTE. LTD.

Ulu-Khachino

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

GBE4809H

ESTIMATE

DATE : 08/10/2020

VEHICLE NO : SBA5995S

MAKE/MODEL : TOYOTA VELLFIRE

ACC DATE : 08/10/2020

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>LIST PRICE</u>			
1	1 REAR WINDSCREEN MOULDING <i>acc 188.45</i>	\$ 297.45	\$ 297.45
2	1 REAR TAILGATE <i>Body</i>	\$ 1,997.42	\$ 1,997.42
3	2 REAR TAILGATE HINGE RH/LH <i>11</i>	\$ 78.20	\$ 156.40 X
4	2 REAR TAILGATE ABSORBER RH / LH <i>11</i>	\$ 299.60	\$ 599.20 X
5	1 REAR TAILGATE RUBBER LH (POWER GATE CONTROL SENSOR) <i>11</i>	\$ 405.22	\$ 405.22 X
6	1 REAR TAILGATE FRAME RUBBER <i>Weatherstrip 7m</i>	\$ 399.45	\$ 399.45
7	1 REAR TAILGATE LOCK <i>20/shut</i>	\$ 509.43	\$ 509.43
8	1 REAR TAILGATE LOCK CATCH <i>11</i>	\$ 43.10	\$ 43.10 X
9	1 REAR TAILGATE KEYLESS SMART <i>cu</i>	\$ 243.50	\$ 243.50
10	1 REAR TAILGATE KEYLESS BUZZLE <i>cu</i>	\$ 220.35	\$ 220.35
11	1 REAR TAILGATE INNER TRIM <i>Def/cu</i>	\$ 718.13	\$ 718.13
12	1 REAR TAILGATE POWER GATE CONTROL SWITCH <i>shut/cu</i>	\$ 309.14	\$ 309.14
13	1 REAR TAILGATE EMBELM ' VELLFIRE ' <i>acc</i>	\$ 96.80	\$ 96.80
14	1 REAR TAILGATE EMBLEM ' V6 ' <i>acc</i>	\$ 95.10	\$ 95.10
15	1 REAR TAILGATE REFLECTOR LH <i>11</i>	\$ 499.35	\$ 499.36 X
16	1 REAR TAILLAMP LH <i>scu/cu</i>	\$ 695.43	\$ 695.43
17	1 REAR TAILLAMP LOWER APRON GARNISH LH <i>de</i>	\$ 266.80	\$ 266.80
18	1 REAR TAILLAMP LOWER APRON GARNISH RETAINER LH <i>scu</i>	\$ 131.60	\$ 131.60
19	1 REAR BUMPER <i>de 1755.10</i>	\$ 1,918.43	\$ 1,918.43
20	1 REAR BUMPER TOW COVER LH <i>de</i>	\$ 69.10	\$ 69.10
21	1 REAR BUMPER BRACKET LH <i>scu</i>	\$ 145.20	\$ 145.20 X
22	2 REAR BUMPER PDC SENSOR <i>shut</i>	\$ 399.45	\$ 798.90
23	2 REAR BUMPER SIDE RETAINER RH / LH <i>11scu</i>	\$ 145.23	\$ 290.46 1pc
24	1 REAR END PANEL <i>Body</i>	\$ 755.23	\$ 755.23
25	1 REAR END PANEL GARNISH <i>11</i>	\$ 395.45	\$ 395.45
26	1 REAR SPARE TYRE PANEL <i>R</i>	\$ 798.50	\$ 798.50 X
27	1 REAR SPARE TYRE PANEL TRIM <i>scu</i>	\$ 509.40	\$ 509.40 X
28	1 REAR SPARE TYRE PANEL CARDBOARD - CENTRE <i>11scu</i>	\$ 335.20	\$ 335.20
29	2 REAR SPARE TYRE PANEL CARDBOARD RH / LH <i>11scu</i>	\$ 394.45	\$ 788.90 1pc
30	1 REAR FENDER INNER TRIM LH <i>Def/cu</i>	\$ 899.45	\$ 899.45
			\$ 15,388.10
		LESS -25%	\$ 3,847.02
		TOTAL	\$ 11,541.07

11419.71
257
8864.78

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
<u>SPECIAL NETT ITEMS</u>			
1	1 REAR WINDSCREEN SPONGE TAPE <i>ner</i>		\$ 20.00 ✓
2	1SET REAR WINDSCREEN SEALANT <i>ner</i>		\$ 80.00 <i>40</i>
3	1SET REAR BUMPER CLIPS <i>ner</i>		\$ 35.00 ✓
			<u>\$ 135.00</u>
 <u>LABOUR CHARGES :</u>			
1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, REAR SPARE TYRE PANEL AND REPLACE ACCIDENT PARTS		\$ 1,200.00 <i>800</i>
2	TO SPRAY PAINTING ON ACCIDENT PORTION		\$ 1,200.00 <i>900</i>
3	TO CHECK WIRING		\$ 30.00 ✓
4	TO REMOVE AND REFIX REAR WINDSCREEN		\$ 120.00 ✓
5	TO TRANSFER REAR TAILGATE PARTS		\$ 100.00 <i>60</i>
6	TO REMOVE AND REFIX CUSHION AND INNER TRIM		\$ 120.00 <i>80</i>
7	TO REFIX RESERVE CAMERA, REAR CAMERA AND REPLACE REVERSE SENSOR		\$ 150.00 <i>50</i>
8	TO REMOVE, REFIX REAR EXHAUST BOX	<i>11</i>	\$ 120.00 <i>X</i>
9	TO REMOVE, REFIX FUEL TANK	<i>11</i>	\$ 120.00 <i>X</i>
10	TO TUFF - KOTE		\$ 90.00 <i>60</i>
TOTAL			<u>\$ 3,250.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 14,926.07

We hereby agree to hence notify
the Insurer of the following:

- To resurvey the vehicle spray painting
- To resurvey the vehicle part(s) during resurvey
- To resurvey the vehicle part(s) to confirmation
- This estimate is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-226478
S.W-95.00
L-2100.00
10759.98
202
8657.