

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

08/10/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 08/10/2020

Estimated repair cost for vehicle no: GBK6386RM NISSAN CABSTAR 3.0 M '17

CHASSIS: JN1SC2F24Z0859641

S/N	QTY	Items / Nett	U/price	Amount
1	1	Rear Tail Gate <i>Denked</i>		\$1,399.70 ✓
2	2	Rear Tailgate Top Side Handle <i>Not m</i>	\$185.10	\$370.20 X.
3	2	Rear Tailgate Lower Side Lock <i>Not m</i>	\$48.20	\$96.40 X.
4	4	Rear Tailgate Lower Side Hinges <i>1 piece but</i>	\$147.30	\$589.20 147.30
5	2	Rear Tailgate Lower Side Bracket <i>Not m</i>	\$125.50	\$251.00 X
6	4	Rear Tailgate Lower Side Bracket Stopper Rubber <i>Not m</i>	\$12.10	\$48.40 X.
7	1	Rear Tailgate Lower Member <i>Not m</i>		\$418.80 X
8	2	Rear Tail Lamp <i>LH cut, RH cut</i>	\$248.60	\$497.20 ✓
9	2	Rear Tail Lamp Bracket <i>RH Best</i>	\$111.20	\$222.40 111.20
10	1	Rear Number Plate Lamp <i>Not m</i>		\$67.50 X
11	1	Rear Number Plate Bracket <i>Best</i>		\$175.50 ✓
12	1	Rear Spare Tyre Lock <i>Denked</i>		\$238.30 ✓
13	2	Rear Exhaust Mounting <i>Not m</i>	\$33.50	\$67.00 X
14	1	Rear Floor Panel <i>Not m</i>		\$10,000.00 X.

2569.20

2312.28

Subtotal:- \$14,441.60

S/N	QTY	Items / Special Nett	U/price	Amount
15	1	Rear Tailgate 70 Km/h Sticker <i>Not m</i>		\$30.00 15
16	2	Rear Tailgate Reflector Sticker <i>Not m</i>	\$20.00	\$40.00 20.
17	1	Rear Tailgate Nissan Sticker <i>Not m</i>		\$80.00 ✓
18	2	Rear Spare Tyre <i>Not m</i>	\$380.00	\$760.00 X
19	1	Rear Reverse Camera <i>Denked</i>		\$850.00 X 380
20	1	Rear Reverse Sensor <i>Denked</i>		\$350.00 200
21	1	Rear Number Plate <i>Best</i>		\$50.00 30
22	1	Rear Exhaust <i>Best</i>		\$884.00 X
23	1	Rear Center Exhaust <i>Not m</i>		\$916.00 X.

1609

Subtotal:- \$3,960.00

Labour charges

To remove & refit reverse camera

\$180.00 X

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit rear & center exhaust

~~\$380.00~~ X 80

To remove & refit rear tailgate aluminium

\$350.00 X

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 40

Towing fee

\$150.00 X

Panel beating

1000
~~\$1,600.00~~ 400

Spray painting

~~\$1,600.00~~ 400

Subtotal:- \$4,610.00

Total:- \$23,011.60

total: 4921.28

4/s: 3.9k.

0\$ pays.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3.9k.

0\$ pays.